

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

JAN 05 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*NAB1600757988*

*10137*

**OPERATOR**

Initial Report  Final Report

<b>Name of Company</b> Devon Energy Production Company	<b>Contact</b> Rudy Zuniga Production Foreman
<b>Address</b> 6488 Seven Rivers Hwy Artesia, NM 88210	<b>Telephone No.</b> 575-390-5435
<b>Facility Name</b> Acme 15 Fed Com 1	<b>Facility Type</b> Gas

<b>Surface Owner</b> Federal	<b>Mineral Owner</b> Federal	<b>API No</b> 30-015-36748
------------------------------	------------------------------	----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	15	19S	31E	1650	South	1650	East	Eddy

**Latitude:** N 32°65'76.22"

**Longitude:** W -103°85'34.40"

**NATURE OF RELEASE**


<b>Type of Release Spill</b> Gas	<b>Volume of Release</b> 60 MCF	<b>Volume Recovered</b> 0 MCF
<b>Source of Release</b> Stack Pack	<b>Date and Hour of Occurrence</b> 12.29.2015 @ 1:34 PM	<b>Date and Hour of Discovery</b> 12.29.2015 @ 1:34 PM
<b>Was Immediate Notice Given?</b> <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	<b>If YES, To Whom?</b> N/A	
<b>By Whom?</b> N/A	<b>Date and Hour</b> N/A	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse</b> N/A	

**If a Watercourse was Impacted, Describe Fully.\***  
N/A

**Describe Cause of Problem and Remedial Action Taken.\***  
Stack pack was popping off due to the DCP slam valve being closed. This caused a 60 MCF gas release. Well was shut in to prevent further release. Waiting on DCP to open the valve.

**Describe Area Affected and Cleanup Action Taken.\***  
60 MCF of gas was release from the stack pack.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Corina Moya	Approved by Environmental Specialist: 	
Title: <b>Field Admin Support</b>	Approval Date: <i>1/7/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>corina.moya@dvn.com</i>	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: 1.5.2016 Phone: 575.746.5559		

\* Attach Additional Sheets If Necessary

*2RP-3475*