

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT
Form C-141
Revised August 8, 2011

DEC 31 2015
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1100557588

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>110190</i>	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Cedar Canyon 28 Federal #6	Facility Type	New drill pad
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-43234

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	28	24S	29E					Eddy County, NM

Latitude N 32.18604° Longitude W 103.98119°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	215 bbls	Volume Recovered	117 bbls
Source of Release	Manhole cover on rental frac tank was left untightened	Date and Hour of Occurrence	12/20/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson-NMOCD; Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International	Date and Hour	12/21/2015 @ 1:02 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The manhole cover on a rental frac tank was left untightened spilling 215 bbls of oil onto the ground. A vacuum truck recovered 117 bbls of oil and the manhole cover was tightened.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 200' x 200' on location. Remediation will be completed in accordance with a remediation plan approved by both NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Casey Summers</i>	OIL CONSERVATION DIVISION	
Printed Name: Casey Summers	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: NM Environmental Advisor	Approval Date: <i>11/5/16</i>	Expiration Date: <i>NA</i>
E-mail Address: Casey.Summers@oxy.com	Remediation Approved per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: <i>12/30/15</i> Phone: (575) 513-8289	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>2/15/16</i>	

* Attach Additional Sheets If Necessary

2RP-3472