

JAN 20 2016

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210.
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1602154960

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2160737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV BS 008H (Future Riser SWD Line)	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 3001539508
------------------------	------------------------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	14	25s	30E	300		1980		Eddy

Latitude: 32.13050 Longitude: 103.84248

NATURE OF RELEASE

Type of Release: Produced Water/ Crude Oil	Volume of Release 38 barrels PW and 38 barrels oil	Volume Recovered: 20 barrels oil and 20 barrels PW
Source of Release: Corrosion to SWD future riser	Date and Hour of Occurrence: 1-15-16 @ 11:00am	Date and Hour of Discovery: 1-15-16 @ 12:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Jim Amos BLM	
By Whom? Bradley Blevins	Date and Hour 1-15-16 @ 1:45pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
BOPCO EHS was notified of a release that occurred on the riser future near the PLU CVX JV BS 008H. A vacuum truck was called to location and was able to recover 20 barrels of oil and 20 barrels of PW.

Describe Area Affected and Cleanup Action Taken.*
The release area ran along the road and into the pasture area near the intersection of Buck Jackson and Rock Dove rd. A vacuum truck was called to location and was able to recover 20 barrels of oil and 20 barrels of PW. An initial scrape of the flow path and sampling event will take place once the one call is active.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: <i>1/21/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: bblevins@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: <i>1-20-16</i> Phone: 432-214-3704	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *2/22/16*

2RP-3507