NM OIL CONSERVATION

ð.

ARTESTA DISTRICT	
Submit One Copy To Appropriate District 0 8 2016 State of New Me Office FEB 0 8 Energy, Minerals and Natur	
1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 RECEIVEBIL CONSERVATION	WELL API NO.
District III 1220 South St. Fran	of Dr. D. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87	SIALE I FEE A
1220 S, St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO PROPOSALS.)	R SUCH Spiketail 5 State (SWD)
1. Type of Well: XOil Well Gas Well Other	8. Well Number 1
2. Name of Operator Cimarex Energy Co of Colorado	9. OGRID Number 162683
3. Address of Operator	10. Pool name or Wildcat
202 S. Cheyenne Ave, Suite 1000, Tulsa OK 741 4. Well Location	03 SWD Cisco Canyon
Unit Letter_K 26:10 feet from the S line and 1980 feet from the W line	
Section 05 Township 17S Range 29E NMPM EddyCounty	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3653 GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON FINDER PLUG AND ABANDON FINDER PLANS	
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL	COMMENCE DRILLING OPNS. P AND A
OTHER: Image: Content of the conten	
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 	
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LE <u>TTER, SECTION, TOWNSHIP, AND RANGE.</u> All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
🔀 The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
Arando Ila Ida	
SIGNATURE THUNDA SMUMAN_TITLE B	egulatory TechDATE 02/03/2016_
For State Use Only	rsheldon@cimarex.comPHONE: 918-295-1709
APPROVED BY: Jon Morales TITLE Complicence Obiles DATE Hight	
Oth-Belease.	

1

.