

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-25635

Release Notification and Corrective Action

11/11/06 0608051335

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Thunderbolt Petroleum	160017	Contact	Robert Lee
Address	P.O. Box 10523, Midland, TX 79702		Telephone No.	432-682-1251
Facility Name	Thunderbolt Pet. Tank Battery		Facility Type	Oil Production Battery
Surface Owner	State of New Mexico	State of New Mexico	Lease No. LG-4524	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	16	18S	29E	2310	South	990	West	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced water and Sludge	Volume of Release	25 bbls	Volume Recovered	0
Source of Release		Date and Hour of Occurrence	3/17/2005	Date and Hour of Discovery	3/18/2005
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RECEIVED

JAN 27 2006

OUR-ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Water hauler pumped water into primary water tank that overflowed into the secondary overflow tank, then onto the ground. Remediation and clean up of release and pad site has been completed.

Describe Area Affected and Cleanup Action Taken.*

Approximately 5000 sq. ft. of surface area was impacted by the release. A proposed remediation plan is attached to this correspondence. Release has been remediated in place using cow manure and gypsum. Pad clean has been cleaned of staining and fresh soil in place of removed stained soil. A firewall has been place around tank battery and small transfer pump.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Joseph A. Baca</i>		OIL CONSERVATION DIVISION	
Printed Name: Joseph A. Baca, PG		Approved by District Supervisor: TIM GUM by MB <i>W. B. B...</i>	
Title: Project Manager		Approval Date: <i>3/21/06</i>	Expiration Date:
E-mail Address: skipb@t3wireless.com		Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: January 25, 2006 Phone: 432-682-7709			

* Attach Additional Sheets If Necessary