

NM OIL CONSERVATION

ARTESIA DISTRICT

MAR 10 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NAB1607039088

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <u>Linn Operating Inc.</u>	Contact <u>EL Gonzales</u>
Address <u>2130 W Bender Blvd Hobbs, NM 88240</u>	Telephone No. <u>575-738-1739</u>
Facility Name <u>Skelly #67</u>	Facility Type <u>Plugged injection well</u>

Surface Owner <u>Federal</u>	Mineral Owner <u>Federal</u>	Lease No. <u>30-015-05339</u>
------------------------------	------------------------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	21	17S	31E	1650	S	1980	E	Eddy

Latitude 32 49' 2.37" N Longitude 103 52' 20.601" W

NATURE OF RELEASE



Type of Release Produced Water	Volume of Release <u>250</u>	Volume Recovered <u>225</u>
Source of Release <u>Injection line</u>	Date and Hour of Occurrence <u>3/8/16</u>	Date and Hour of Discovery <u>3/8/16</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Mike Bratcher NMOC, James Amos BLM</u>	
By Whom? <u>Dennis Potter</u>	Date and Hour <u>08:00</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A plug in the fiberglass line failed.

Describe Area Affected and Cleanup Action Taken.* The line was shut in. DFSI was called in to scrape the affected area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: <u>EL Gonzales</u>	Approved by District Supervisor: 	
Title: <u>Production Supervisor</u>	Approval Date: <u>3/10/16</u>	Expiration Date: <u>NIA</u>
E-mail Address: <u>elgonzales@linenergy.com</u>	Conditions of Approval:	
Date: <u>3/9/2016</u> Phone: <u>575-504-8002</u>	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 4/10/16

2RP-3606