

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

MAY 10 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1613157015

Name of Company Pyote Water Systems, LLC		OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address 400 W Illinois St E 900		Contact Jerry Burton NM OP MGR	
Facility Name DORSTATE SWD		Telephone No. 432-448-4917 or 432-448-5323 office in Calrsbad	
Facility Type			
Surface Owner state/trust land	Mineral Owner state trust land	API No. 30-015-23728	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy County
-------------	---------	----------	-------	---------------	------------------	---------------	----------------	-----------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release production water	Volume of Release 500 bbl	Volume Recovered 500 bbl
Source of Release valve/seal broke	Date and Hour of Occurrence 5-2-16	Date and Hour of Discovery 5-2-16
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jerry Burton	
By Whom? Kenny G contract pumper for PWS	Date and Hour 5-2-16 9:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

centripycal seal and stuffing box went out, caused a spill in CONTAINMENT****CONTAINMET NOT BREECHED! On the pad it is the driver's duty to vclean up sumps after they are done unloading, if failure to do so, there tires splash the water to where it stains, but ther has no other realease reported per Jerry Burton. load lines 1 & 2 has stains/possible from water splashing when driver's leave. Amber Groves from the state was present

Describe Area Affected and Cleanup Action Taken.*

500bbl contained/ we called in vac trucks D& H trucking and BT services to cleanup containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jerry Burton	Approved by Environmental Specialist: 	Accepted for record NMOCD
Title: NM OP MGR	Approval Date: 5/10/16	Expiration Date: N/A
E-mail Address: JERRY@PYOTEWATERSYSTEMS.COM	Conditions of Approval: <input checked="" type="checkbox"/> Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Submit Remediation Proposal NO	
Date: 5-2-16 (REVISED) Phone: 432-448-4917	LATER THAN: 01/12/16	

* Attach Additional Sheets If Necessary

OR 432-448-5323 OFFICE

2RD. 3087