

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action


NAB 10/4/2011

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Walker State Tank Battery	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	Lease No.

LOCATION OF RELEASE <i>30-015-22015</i>								
Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
0	27	17S	29E					Eddy

Latitude 32 48.065 Longitude 104 09.671

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	200bbls	Volume Recovered	18bbls
Source of Release	Hole in tank	Date and Hour of Occurrence	08/08/2011	Date and Hour of Discovery	08/08/2011 8:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Josh Russo	Date and Hour	08/08/2011 2:04 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A hole developed in the bottom of an oil tank. The tank has been removed and is in the process of being repaired.					
Describe Area Affected and Cleanup Action Taken.*					
Initially roughly 200bbls of oil were released from the tank and we were able to recover 18bbls with a vacuum truck. The spill area will be scraped to remove surface contamination. BBC will sample the spill site area to identify any possible contamination from the release. We will notify the OCD prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Josh Russo		Approved by District Supervisor: Accepted for record NMOCD			
Title: HSE Coordinator		Approval Date: <i>5/19/16</i>		Expiration Date: <i>N/A</i>	
E-mail Address: jrusso@conchoresources.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 08/17/2011		Phone: 432-212-2399			

* Attach Additional Sheets If Necessary

ARP-3701