State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary

Tony Delfin

Deputy Cabinet Secretary

David Catanach, Director Oil Conservation Division



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

07-Jun-16

BOPCO, L.P. P. O. BOX 2760 MIDLAND TX 79702

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

POKER LAKE UNIT CVX JV PC No.004H Inspection				P-5-25S-30E *Significant	30-015-36998-00-00 Corrective	
Date	Type Inspection	Inspector	Violation?	Non-Compliance?	Action Due By:	Inspection No.
06/07/2016	Routine/Periodic	Gilbert Cordero	Yes	No	9/10/2016	iGC1615938142
Comments o	on Inspection: LOCATION	SIGN IS INCORRECT	- PLU PIEI	RCE CANYON 5 STA	ATE 001H	•
POKER LAKE CVX JV BS No.020H				P-2-25S-30E	30-015-40661-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/07/2016	Routine/Periodic	Gilbert Cordero	Yes	No	9/10/2016	iGC1615935052
Comments of	n Inspection: LOCATION	SIGN IS INCORRECT	- PLU BIG	SINKS STATE 002H	i	

INSPECTION DETAIL SECTION

POKER LAKE UNIT CVX JV BS No.023H N-2-25S-30E 30-015-41392-00-00 Inspection *Significant Corrective Type Inspection Inspector Inspection No. Violation? Non-Compliance? Action Due By: 06/07/2016 Routine/Periodic Gilbert Cordero iGC1615933952 Yes 9/10/2016

Comments on Inspection: LOCATION SIGN IS INCORRECT - PLU BIG SINKS STATE 003H

Oil Conservation Division * 811 S. First St. * Artesia, New Mexico 88210 Phone: 575-748-1283 * Fax: 575-748-9720 * http://www.emnrd.state.nm.us

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely,

COMPLIANCE OFFICER

Artesia OCD District Office

* Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas.

Oil Conservation Division * 811 S. First St. * Artesia, New Mexico 88210 Phone: 575-748-1283 * Fax: 575-748-9720 * http://www.emnrd.state.nm.us