State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary

David Catanach, Director

Tony Delfin

Deputy Cabinet Secretary

Oil Conservation Division



Response Required - Deadline Enclosed

21-Jun-16

TANDEM ENERGY CORPORATION

2700 POST OAK BLVD SUITE 1000 HOUSTON TX 77056-

LETTER OF VIOLATION - Inactive Well(s)

Dear Operator:

A review of our records and recent inspection(s) indicate that the subject well(s) has been shut-in for an extended period of time. Rule 201 of the Rules and Regulation of the Oil Conservation Division provides that a well may be shut-in no longer than sixty days after suspension of drilling operations, upon determining that ther well is no longer usable (e.g., a dry hole), or one year after last production. To comply with guidelines as established in the Rules and Regulations, corrective actions must be taken immediately and the well(s) brought into compliance.

The detail section below indicates preliminary findings and/or probable nature of the violation.

The following options are available:

- 1. Immediately restore the well(s) to production, injection or disposal as applicable.
- 2. Request Temporary Abandoned status pursuant to Rule 203, which requires that you set a plug and conduct a mechanical integrity test.
- 3. Submit a proposal to 'Plug and Abandon' the well(s) pursuant to Rule 202, proceed with plugging procedures on a timely basis after the proposal has been evaluated, amended and/or approved.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

IDLE WELL INSPECTION DETAIL SECTION				
HEARD A 003		G-27-16S-30E	30-015-21690-00-00	Inspection No. iTM1617349595
Inspection Date:	: 6/21/2016 1:46:32 PM		Corrective Action Due by: 9/24/2016	
Type Inspection		Inspector	Violation	*Significant Non-Compliance?
Routine/Periodic		Tony Morales	Yes	No
Comments on Insp	ection:	Idle Well (Rule 19.15.25.8) LINE. OLD TUBING.		PJ. NO ELECTRIC METER. NO FLOW
HEARD A 004		H-27-16S-30E	30-015-21861-00-00	Inspection No. iTM1617349369

Inspection Date: 6/21/2016 1:42:44 PM

Corrective Action Due by: 9/24/2016

Type Inspection

Inspector

Violation?

*Significant Non-Compliance?

Routine/Periodic

Tony Morales

No

Comments on Inspection:

Idle Well (Rule 19.15.25.8)

Yes

OUT OF WELL HEAD.

NO PJ. OLD FLOW LINE SUCKER ROD

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely,

* Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas.