

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JUL 07 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1619027282

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Company 6137	Contact Danny Velo, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-703-3360
Facility Name Federal HJ-27 I	Facility Type Oil

Surface Owner Federal	Mineral Owner Federal	API No 30-015-25780
-----------------------	-----------------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	27	19S	31E	1880'	North	660'	FWL	Eddy

Latitude: 32.7573929

Longitude: -104.0829773

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 7bbls	Volume Recovered 0bbls
Source of Release Nipple on water tank	Date and Hour of Occurrence July 4, 2016 @ 10:00 AM	Date and Hour of Discovery July 4, 2016 @ 10:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher, OCD	
By Whom? Danny Velo, Production Foreman	Date and Hour Shelly Tucker, BLM July 7, 2016 @ 2:45 PM Mike Bratcher, OCD July 7, 2016 @ 1:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

A nipple from the water tank was either stepped on or laid on by a cow causing the threads on the nipple to break. The tank was taken out of service until repairs can be made.

Describe Area Affected and Cleanup Action Taken.*

Approximately 7bbls produced water was released into bermed dirt containment. All fluid remained in containment with 0bbls recovered. An environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Signed By: Mike Bratcher Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 7/8/16	Expiration Date: N/A
E-mail Address: Sheila.Fisher@dvn.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 7/7/16 Phone: 575.746.1829	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 7/8/16	

* Attach Additional Sheets If Necessary

2RD-3745