

**NM OIL CONSERVATION**

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED**

UL 1 3 2016

**Release Notification and Corrective Action**

*NAB 11019750175*

**OPERATOR**

Initial Report  Final Report

Name of Company:	COG Operating LLC <i>289137</i>	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	HONEY GRAHAM STATE COM #004H	Facility Type:	Tank Battery
Surface Owner:	State	Mineral Owner:	API No. 30-015-41379

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	29	26S	28E	330'	North	1980'	East	Eddy

Latitude 32.019558 Longitude 104.1071777

**NATURE OF RELEASE**

Type of Release:	Produced Water	Volume of Release:	5bbls of Produced Water	Volume Recovered:	4bbls of Produced Water
Source of Release:	Heater Treater	Date and Hour of Occurrence:	7/11/2016 10:00:00 AM	Date and Hour of Discovery:	7/11/2016 10:00:00 AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour:			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A hole developed in the thermo coupler, the thermo coupler has been replaced with a new one.					
Describe Area Affected and Cleanup Action Taken.*					
The release was contained within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment will be cleaned and the facility will be put back into operation. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:	<i>Robert Grubbs Jr.</i>	<b>OIL CONSERVATION DIVISION</b>			
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist: <i>[Signature]</i>			
Title:	Senior Environmental Coordinator	Approval Date:	7/14/16	Expiration Date:	N/A
E-mail Address:	rgrubbs@concho.com	Conditions of Approval:			
Date:	July 13, 2016	Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>			
Phone:	432-683-7443	<b>SUBMIT REMEDIATION PROPOSAL NO</b>			

\* Attach Additional Sheets If Necessary

LATER THAN: 7/18/16

*JRP-3780*