State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary

Tony Delfin

Deputy Cabinet Secretary

David Catanach, DirectorOil Conservation Division

Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

19-Jul-16

FINNEY OIL COMPANY

¿PO BOX 1569

ARTESIA NM 88211-1569

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

TWIN LAKES No.002				M-28-18S-28E	30-015-02058-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective . Action Due By:	Inspection No.
07/19/2016	Routine/Periodic Violations	Tony Morales	Yes	No	10/22/2016	iTM1620139602
	General Housekeeping (Rule	114)				
Comments	on Inspection: OK. All E	quipment and Location in	Good Shape	. PJ. OLD PJ ON LO	OCATION.	
TWIN LAKES No.007				M-28-18S-28E	30-015-02062-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/19/2016	Routine/Periodic	Tony Morales	Yes	No	10/22/2016	iTM1620139314
	Violations	•				
	Absent Well Identification Sig	gns (Rule 103)				
Comments of	on Inspection: OK. All E	- quipment and Location in	Good Shape.	LOCATION SIGN	NOT VISIBLE.	

TWIN LAKES No.010

L-28-18S-28E

30-015-06112-00-00

Inspection

07/19/2016

Type Inspection Date

Inspector

Violation?

*Significant Non-Compliance?

Corrective Action Due By:

Inspection No.

Tony Morales

Yes

No

10/22/2016

iTM1620139049

Violations

Routine/Periodic

General Housekeeping (Rule 114)

Comments on Inspection:

OK. All Equipment and Location in Good Shape. PJ. PULLING UNIT ON LOCATION.

STAINING AROUND WELL HEAD. TANK BATTERY STAINING.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.