

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 20 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1620727144

Name of Company Oxy Permian Ltd. 110696		Contact Casey Summers	
Address 6 Desta Drive, Midland, TX 79705		Telephone No. (575) 513-8289	
Facility Name Pure Gold B Federal #4		Facility Type Well	
Surface Owner BLM		Mineral Owner	
		API No. 30-015-27238	

OPERATOR

☒ Initial Report ☐ Final Report

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	20	23S	31E					Eddy

Latitude N 32.28449° Longitude W 103.79334°

NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release 15 bbls oil, 2 bbls produced water	Volume Recovered 10 bbls
Source of Release Livestock broke off well head sensor nipple	Date and Hour of Occurrence 07/14/2016	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM	
By Whom? Jennifer Gilkey @ BBC International Inc.	Date and Hour 07/14/2016 @ 4:28 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



Livestock broke off the well head sensor nipple causing a release of 15 bbls of oil and 2 bbls of produced water. A vacuum truck recovered 10 bbls of fluids and the nipple was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 150' x 50' both on and off location. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Casey Summers	Approval Date: 7/21/16	Expiration Date: N/A
Title: NM Environmental Advisor	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
E-mail Address: Casey.Summers@oxy.com	SUBMIT REMEDIATION PROPOSAL NO	
Date: 7-18-16 Phone: (575) 513-8289	LATER THAN: 8/25/16	

* Attach Additional Sheets If Necessary

2RP-3795