State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin
Cabinet Secretary

Tony Delfin
Deputy Cabinet Secretary

David Catanach, Director
Oil Conservation Division



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

20-Jul-16

LINN OPERATING, INC. 600 TRAVIS STREET SUITE 4900 HOUSTON TX 77002-7002

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

		1/2	VSPECTION	V DETAIL	SECTION		
WELCH No Inspection Date	0.001 Type Inspection	Ins	pector	Violation?	I-30-18S-28E *Significant Non-Compliance?	30-015-25306-00-00 Corrective Action Due By:	Inspection No.
07/20/2016	Routine/Period Violations	ic To:	ny Morales	Yes	No	10/23/2016	iTM1620233085
	General Housekee	oing (Rule 114)					
Comments on Inspection:		OK, All Equipment a BATTERY HEATER				RIES OK. OLD TANK	

LINN Energy Regulatory Department

JUL 26 2016


In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCO District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.


*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.



WELCH No. 001 Inspection No. iTM1620233085 Before Photo



WELCH No. 001 Inspection No. ITM1620233085 Before Photo




WELCH No. 001 Inspection No. iTM1620233085 Post Cleanup




WELCH No. 001 Inspection No. iTM1620233085 Post Cleanup



WELCH No. 001 Inspection No. ITM1620233085 Post Cleanup




WELCH No. 001 Inspection No. iTM1620233085 Post Cleanup





WELCH No. 001 Inspection No. iTM1620233085 Post Cleanup



WELCH No. 001 Inspection No. iTM1620233085 Post Cleanup