

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

SEP 20 2016

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED  
to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

**NAB11626654019**

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	PO Box 4294; Houston, TX 77210	Telephone No.	(575) 513-8289
Facility Name	Federal 29 #008 CTB	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-27266

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	29	23S	31E					Eddy County, NM

Latitude N 32.26896° Longitude W 103.80605°

## NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	1.5 bbls oil, 3.5 bbls produced water	Volume Recovered	4 bbls
Source of Release	Excessive water caused the tank to spill over	Date and Hour of Occurrence	09/07/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson-NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy Purvis	Date and Hour	09/07/2016 @ 3:24pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Excessive water caused the tank to spill over 1.5 bbls of oil and 3.5 bbls of produced water. A vacuum truck recovered 4 bbls of free-standing fluids.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 15' x 30' on location inside containment. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Casey Summers	Approved by Environmental Specialist	Signed By: <i>[Signature]</i>
Title: NM Environmental Advisor	Approval Date: 9/22/16	Expiration Date: N/A
E-mail Address: Casey.Summers@oxy.com	Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 9-20-16 Phone: (575) 513-8289	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 10/26/16	

\* Attach Additional Sheets If Necessary

2RP-3901