

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 22 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1626756642

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Company 16137 Contact Jake Harrington, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210 Telephone No. 432-214-5175
Facility Name Cotton Draw Unit SWD 181 transfer line Facility Type Salt Water Disposal

Surface Owner Federal Mineral Owner Federal API No 30-015-41649

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	36	24S	31E	1568	North	1189	East	Eddy

Latitude: 32.1767349

Longitude: -103.7268524

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced water	15bbls	0bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Transfer line	September 20, 2016 @ 10:40 AM	September 20, 2016 @ 10:40 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher, OCD	
By Whom? Mike McMahan, Asst. Production Foreman	Date and Hour Shelly Tucker, BLM September 20, 2016 @ 4:00 PM Mike Bratcher, OCD September 20, 2016 @ 4:05 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Due to erosion the main steel transfer line for the Salt Water Disposal developed a hole. The line was immediately shut in to stop the release. Repairs have been made and the line is back in service.

Describe Area Affected and Cleanup Action Taken.*

Approximately 15bbls produced water was released in the right of way from the produced water transfer line that carries water to the Cotton Draw Unit SWD 181. This part of the transfer line is located nearest to the Cotton Draw Unit 167H Battery. All fluid stayed in the right of way in approximately an 80'x45' area. 0bbls produced water was recovered from the right of way. An environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION	
Signature: Sheila Fisher	Signed By Mike Bratcher
Printed Name: Sheila Fisher	Approved by Environmental Specialist:
Title: Field Admin Support	Approval Date: 9/23/16 Expiration Date: N/A
E-mail Address: Sheila.fisher@dm.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines
Date: 9/22/16 Phone: 575.748.1829	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

LATER THAN: 10/26/16

2RP-3005