

NM OIL CONSERVATION

ARTESIA DISTRICT

OCT 04 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Submit a copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

NAB 1627849311

Name of Company:	COG Operating LLC <i>229137</i>	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	SRO SWD #104	Facility Type:	Flowline

Surface Owner:	State	Mineral Owner:	API No.	30-015-25864
----------------	-------	----------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	10	26S	28E	1980'	North	1980'	West	Eddy

Latitude 32.0588913 Longitude 104.0774612

NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	20bbls	Volume Recovered:	8bbls
Source of Release:	Steel Flowline	Date and Hour of Occurrence:	10-02-2016 4:00 pm	Date and Hour of Discovery:	10-02-2016 4:00 pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour:			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A 3" steel flowline failed due to age and corrosion. Replaced the bad section with a new joint of 3" steel line.

Describe Area Affected and Cleanup Action Taken.*
This release occurred in the pasture a 20X50 area. All free fluids were burnt up in the fire. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Signed By: <i>Mike Brannon</i>	
Title:	Senior Environmental Coordinator	Approved by Environmental Specialist:	
E-mail Address:	rgrubbs@concho.com	Approval Date:	<i>10/4/16</i> Expiration Date: <i>N/A</i>
Date:	October 4, 2016 Phone: 432-683-7443	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>11/4/16</i>	

* Attach Additional Sheets If Necessary

2RP-3925