

OCT 06 2016

Form C-141

Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED  
Submit to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

*NAB1628633203*

Name of Company: COG Operating LLC <i>229137</i>		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: 600 West Illinois Avenue, Midland TX 79701		Contact: Robert McNeill			
Facility Name: MYOX 29 STATE COM #003H		Telephone No. 432-683-7443			
		Facility Type: Tank Battery			
Surface Owner:	State	Mineral Owner:		API No.	30-015-39404

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	29	25E	29S	330'	South	1870'	West	Eddy

Latitude 32.0941544 Longitude 104.1117859

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 5bbls of Oil & 5bbls of Produced water	Volume Recovered: 5bbls of Oil & 5bbls of Produced water
Source of Release: Sight glass on FWKO	Date and Hour of Occurrence: 10-05-2016 12:00 pm	Date and Hour of Discovery: 10-05-2016 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Sight glass on a FWKO failed due to age. Replaced the sight glass on the FWKO.		
Describe Area Affected and Cleanup Action Taken.* This release occurred within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Signed By: <i>M. T. Brumley</i>	
Title: Senior Environmental Coordinator	Approved by Environmental Specialist:	
E-mail Address: rgrubbs@concho.com	Approval Date: 10/11/16	Expiration Date: N/A
Date: October 6, 2016 Phone: 432-683-7443	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	

\* Attach Additional Sheets If Necessary

LATER THAN: 11/12/16 *2RP-3936*