

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Range Resources Corporation	Contact: Steve Almager	
Address: 100 Throckmorton Ste 1200	Telephone No. (575)394-1485	
Facility Name: SCB Injection Facility	Facility Type: Battery	
Surface Owner	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter	Section 23	Township 23 S	Range 28 E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude: 32.173350N Longitude: 104.033302W

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 300 bbls	Volume Recovered 290 bbls
Source of Release 2" Nipple Eroded Off Check Valve on the H-Pump	Date and Hour of Occurrence 8-15-09 10:45 Am	Date and Hour of Discovery 8-15-09 10:45 Am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCD	
By Whom? Sergio Contreras, SESI	Date and Hour 8/17/09 9:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A 2" nipple eroded off the end of the check valve on the H-Pump. The pump failed to shut off and resulted in water pumping into the lined tank battery and overflowing the firewalls.

Describe Area Affected and Cleanup Action Taken.\*

SESI was contacted for assessment. Area will be delineated and an appropriate work plan submitted upon results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Steve Almager		Approved by District Supervisor: 	
Title: Production Supervisor II		Approval Date: 8/24/09	Expiration Date: N/A
E-mail Address: salmager@rangeresources.com		Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 8/18/09	Phone: (575) 394-1485		

Attach Additional Sheets If Necessary

22P-350