

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
VO

Form C-103
Revised July 18, 2013

WELL API NO. 30-015-10843
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name COTTON DRAW UNIT
8. Well Number 65
9. OGRID Number 6137
10. Pool name or Wildcat SWD; CHERRY CANYON
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
DEVON ENERGY PRODUCTION CO LP

3. Address of Operator
PO BOX 250, ARTESIA, NM 88311

4. Well Location

Unit Letter G: 1980 feet from the NORTH line and 1980 feet from the EAST line
Section 2 Township 25S Range 31E NMPM County EDDY

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

This well was plugged and abandoned on 3/21/2014. P&A Reclamation is not possible since there is an active battery on the location pad, but environmental remediation has been completed (copy of report attached).

Devon Energy respectfully requests that this well be released from the P&A reclamation requirements only. Thank you.

Spud Date:

Rig Release Date:

OK
HMP

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Menoud TITLE Field Admin Support DATE 10/20/2016

Type or print name Denise Menoud E-mail address: denise.menoud@devn.com PHONE: 575-746-5544

For State Use Only

APPROVED BY: Robert J. Bird TITLE COMPLIANCE OFFICER DATE 10/21/2016

Conditions of Approval (if any):