

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NOV 15 2016

Form C-141
Revised March 17, 1999

RECEIVED Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NAB1032135662

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	BTA Oil Producers LLC <i>210297</i>	Contact <input type="checkbox"/>	Pam Inskeep
Address	104 S. Pecos, Midland, TX 79701	Telephone No. <input type="checkbox"/>	(432) 682-3753
Facility Name	Ogden 20509 JV-P #1 gas flowline 30-015-24206 32.277824, -104.106971	Facility Type <input type="checkbox"/>	Flowline (not in use)

Surface Owner	Onsuresz	Mineral Owner		Lease No. <input type="checkbox"/>	NMNM100335
---------------	----------	---------------	--	------------------------------------	------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County <input type="checkbox"/>
G (batt)	29	23S	28E	1980	North	1830	East	Eddy

NATURE OF RELEASE

Type of Release	Minor	Volume of Release	20 BW	Volume Recovered <input type="checkbox"/>	0
Source of Release	line explosion	Date and Hour of Occurrence	11 pm 07/15/2016	Date and Hour of Discovery <input type="checkbox"/>	11 pm 7/15/2016
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Heather Patterson – NMOCD Carlsbad BLM, Shelly Tucker		
By Whom? <input type="checkbox"/>	Pam Inskeep	Date and Hour <input type="checkbox"/>	4:30 pm 07/18/2016		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

State police called BTA emergency #, field foreman was contacted and pumper went immediately to the location.

Emergency vehicles from Loving County were already there. This is an abandoned gas line. There was some water in the line, 20 BW estimated released from the line.

BTA excavated and sampled, will dispose of at R360. We will evaluate and repair or replace. BTA is consulting with Mike Bratcher on the clean up.

Estimate 25'x10' excavated hole
Estimate 5'x5' original hole

Describe Area Affected and Cleanup Action Taken.*

See above explanation

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Pam Inskeep		Approved by <input type="checkbox"/> District Supervisor: <i>Signed By Mike Bratcher</i>	
Title: Regulatory Administrator	Approval Date: <i>11/16/16</i>	Expiration Date: <i>NIA</i>	
Date: 07/25/2016 Phone: (432) 682-3753	Conditions of Approval:	Attached <input checked="" type="checkbox"/>	

* Attach Additional Sheets If Necessary

ARP-3496