

NOV 29 2016

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1033655690

OPERATOR Initial Report Final Report

Name of Company: COG Operating LLC <i>224137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Skelly 605 Battery	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-015-36885
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter J	Section 14	Township 17S	Range 31E	Feet from the 2460	North/South Line South	Feet from the 2410	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.8341255 Longitude 103.8396072

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 35 bbls	Volume Recovered: 30 bbls
Source of Release: Flowline	Date and Hour of Occurrence: 11/28/2016 10:00 am	Date and Hour of Discovery: 11/28/2016 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Patterson - NMOCD / Ms. Tucker - BLM	
By Whom? Rebecca Haskell	Date and Hour: Monday, 11/28/2016 12:16 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
Fourth-Inch check valve failure. Repaired the check valve.		
Describe Area Affected and Cleanup Action Taken.* This release occurred from a valve box located behind the battery. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area sampled to delineate any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION Signed By: <i>[Signature]</i>	
Printed Name: Rebecca Haskell		
Title: Senior HSE Coordinator	Approved by Environmental Specialist:	Approval Date: <i>11/29/16</i> Expiration Date: <i>N/A</i>
E-mail Address: <i>rhaskell@concho.com</i>	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: <i>11/29/16</i> Phone: 432-683-7443		

* Attach Additional Sheets IF Necessary

2 RP-4015