

Received 6/25/2014

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

NMOCD Dist 2

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

DAB17DD652208

## OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>TH</sup> Street		Telephone No. 575-748-1471
Facility Name Flora AKF State #4	API Number 30-015-32028	Facility Type Pumping Unit

Surface Owner State	Mineral Owner State	Lease No. VO-2597
------------------------	------------------------	----------------------

## LOCATION OF RELEASE

Unit Letter M	Section 2	Township 22S	Range 31E	Feet from the 990	North/South Line South	Feet from the 330	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.41582 Longitude 103.75554

## NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 2 B/O & 3 B/PW	Volume Recovered 0 B/O & 0 B/PW
Source of Release Poly Flow Line	Date and Hour of Occurrence 6/5/2014, AM	Date and Hour of Discovery 6/5/2014, AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*



Poly flow line developed a leak. Isolated line, shut down well(s), called vacuum truck and crew to repaired line.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 35' X 25'. No oil or produced water to recover. The impacted area was brush hog mowed and Micro Blaze applied. **Depth to Ground Water: >100' (approx. 125'), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on described clean-up actions and small amounts released, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature: 	SIGNED BY 	
Printed Name: Robert Asher	Approved by District Supervisor.	
Title: NM Environmental Regulatory Supervisor	Approval Date: 11/6/17	Expiration Date: N/A
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Wednesday, June 25, 2014 Phone: 575-748-4217	2RP- FINAL	

\* Attach Additional Sheets If Necessary

2RP- 4060