

Received 8/6/2014

NMOCD Dist 2

## District I

1625 N. French Dr., Hobbs, NM 88240

## District II

811 S. First St., Artesia, NM 88210

## District III

1000 Rio Brazos Road, Aztec, NM 87410

## District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural ResourcesOil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505Form C-141  
Revised August 8, 2011Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

*NAB 1700 L15/L157*



<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company Yates Petroleum Corporation	Contact Robert Asher		
Address 104 S. 4 <sup>th</sup> Street	Telephone No. 575-748-1471		
Facility Name Jacque AQJ State #7	Facility Type Well Pad		
Surface Owner State	Mineral Owner State	API No. 30-015-33335	

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	34	21S	31E	990	North	1650	West	Eddy

Latitude 32.43937 Longitude 103.76845

## NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 2 B/O & 8 B/PW	Volume Recovered 0 B/O & 0 B/PW
Source of Release Poly flow line	Date and Hour of Occurrence 7/23/2014; PM	Date and Hour of Discovery 7/23/2014; PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* There was a leak in the flow line, causing the release. Well was shut off; called vacuum truck and crew to repair line.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 30 X 20' all on the well pad. Poly line was repaired and backhoe and roustabout crews were called to scape impacted soils from the pad area, those soils were taken to an NMOCD approved facility. <b>Depth to Ground Water: &gt;100' (approximately 175', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: &gt; 1000', SITE RANKING IS 0. Based on minor amounts released, site ranking of zero and impacted soils scaped/hailed, Yates Petroleum Corporation requests closure.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: NM Environmental Regulatory Supervisor	Approval Date: <u>11/6/17</u>	Expiration Date: <u>N/A</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: <u>FINAL</u>	Attached <input type="checkbox"/>
Date: July 24, 2014	2RP-	

\* Attach Additional Sheets If Necessary

2RP-4063