

Received 2/27/2017

NMOCD Dist 2

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Form C-141
Revised August 8, 2011Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR ☒ Initial Report ☒ Final Report

Name of Company Devon Energy Production Company **Contact** Steve McGlasson, Construction/Facilities Foreman

Address 6488 Seven Rivers Hwy Artesia, NM 88210 **Telephone No.** 575-703-2741

Facility Name Laguna Salado South #1 **Facility Type** Gas

Surface Owner Federal **Mineral Owner** Federal **API No** 30-015-26407


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	22	23S	29E	2030	North	1980	West	Eddy

Latitude: N 32.2922554

Longitude: W -103.9748001

NATURE OF RELEASE

Type of Release Produced Water & Oil	Volume of Release 128 BBLS PW & 2BBLS Oil	Volume Recovered 128 BBLS PW & 2BBLS Oil
Source of Release Basic Sediment & Water (BS&W) valve	Date and Hour of Occurrence 2/15/2017 @ 3:00pm	Date and Hour of Discovery 2/15/2017 @ 3:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM-Shelly Tucker OCD-Mike Bratcher	
By Whom? Aaron Kidd, Assistant Construction Foreman	Date and Hour BLM-2/16/2017 @ 10:30am OCD-2/16/2017 @ 10:15am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Construction crews were replacing and updating nozzles and Basic Sediment & Water valves at the Laguna Salado South #1. The BS&W split causing a release of 128 BBLS produced water and 2 BBLS oil into the lined containment. The remaining fluids in the tank were removed by vacuum truck to prevent any further release.		
Describe Area Affected and Cleanup Action Taken.* 128 BBLS of produced water and 2 BBLS of oil were released from a BS&W valve into lined containment. All 128 BBLS of produced water and 2 BBLS of oil remained in lined containment. A vacuum truck was dispatched and recovered all 128 BBLS produced water and 2 BBLS oil. The liner was inspected for holes and none were found. No further action is necessary.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Sarah Gallegos-Troublefield	OIL CONSERVATION DIVISION	
Printed Name: Sarah Gallegos-Troublefield	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 2/28/17	Expiration Date: N/A
E-mail Address: Sarah.Gallegos-Troublefield@dv.com	Conditions of Approval: SEE BELOW:	Attached <input type="checkbox"/>
Date: 2/27/2017 Phone: 575.748.1864		

* Attach Additional Sheets If Necessary

COA: It is OCD's understanding that all impacted material has been removed/replaced, the liner cleaned and inspected for integrity.

2RP- 4/30