

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
State of New Mexico
ARTESIA DISTRICT
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

MAR 08 2017

RECEIVED

Release Notification and Corrective Action

NAB1706938037

OPERATOR Initial Report Final Report

Name of Company EOG Y Resources, Inc.	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-1471	
Facility Name Tombstone BMB State #1	Facility Type Battery	

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-36315
--------------------------	--------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	12	25S	29E	660	North	330	West	Eddy

Latitude 32.15018 Longitude 103.94558

NATURE OF RELEASE

Type of Release Oil & Produced Water	Volume of Release 35 B/PW	Volume Recovered 35 B/PW
Source of Release Heater Treater	Date and Hour of Occurrence 2/19/2017; AM	Date and Hour of Discovery 2/19/2017; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/EOG Resources, Inc.	Date and Hour 2/20/2017; AM * 2/20/17 e-mail 7:22am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A hole developed in the bottom of the heater treater, causing the release. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 50' X 50'. The valves were closed, vacuum trucks were called and a roustabout crew was called to repair the heater. Impacted gravel was excavated /hailed to a NMOCD approved facility. The release occurred within a lined/bermed battery where the liner has not been compromised and is integrally sound. Depth to Ground Water: 50-99' (approximately 60', Section 10, T25S-T29E, per the NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on repairs, impacted gravel removed excavated and all produced water recovered, EOG Y Resources, Inc. requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist:	
Title: Environmental Supervisor	Approval Date: 3/10/17	Expiration Date: NA
E-mail Address: Robert.Asher@eogresources.com	Conditions of Approval: SEE Attached	Attached <input checked="" type="checkbox"/>
Date: March 7, 2017	Phone: 575-748-4217	2RP- FINAL

* Attach Additional Sheets If Necessary

2RP-4138