ĸ	UNITED STATES EPARTMENT OF THE D UREAU OF LAND MANA	NTERIOR NIM	CD OME	M APPROVED 3 NO. 1004-0137 5: January 31, 2018	
	NOTICES AND REPO		5. Lease Serial No.		
Do not use th	is form for proposals to II. Use form 3160-3 (AP	drill or to re-enter an	6. If Indian, Allotte		
SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well Q Oil Well Gas Well Other			7. If Unit or CA/A	 If Unit or CA/Agreement, Name and/or N 8. Well Name and No. EAGLE 34 J FEDERAL 20 	
			8. Well Name and EAGLE 34 J F		
2. Name of Operator LIME ROCK RESOURCES II-A, L.P. E-Mail: MIKE@PIPPINLLC			N 9. API Well No. 30-015-29641		
3a. Address C/O MIKE PIPPIN 3104 N. SULLIVAN		3b. Phone No. (include area code) Ph: 505-327-4573	10. Field and Pool	10. Field and Pool or Exploratory Area RED LAKE,Q-GB-SA 51300	
FARMINGTON, NM 87401 4. Location of Well (Footage, Sec., T., R., M., or Survey Description			11 County or Pari	11. County or Parish, State	
Sec 34 T17S R27E NWSE 1690FSL 1650FEL		, ,		EDDY COUNTY, NM	
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR C	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
□ Notice of Intent	Acidize	Deepen	Production (Start/Resume)	U Water Shut-C	
—	□ Alter Casing	Hydraulic Fracturing	Reclamation	🖸 Well Integrit	
Subsequent Report	🛛 Casing Repair	New Construction	Recomplete	D Other	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon		
	Convert to Injection	Plug Back	Water Disposal		
determined that the site is ready for THIS WORK WAS TO REPA	final inspection.	ERBP @ 1800', & RETURN TH	ling reclamation, have been complet	ed and the operator has	
THIS WORK WAS TO REPA On 12/8/16, dug out cellar & f csg. Cut off 5-1/2" & installed PT welds on 5-1/2" csg to 10 surface. Installed wellhead & 1/12/17, ran 35 jts 2-3/8" 4.7#	final inspection. IR BAD CSG, RETRIEVE found bad 8-5/8" csg belo d 5-1/2" slip X slip collar in 00 psi-OK. Installed 8-5/8 valves. On 1/10/17, MIR # J-55 & 65 jts 2-7/8" 6.5#		HE WELL TO PRODUCTION g below bad surface. vack to ' & TOH. On		
THIS WORK WAS TO REPA On 12/8/16, dug out cellar & f csg. Cut off 5-1/2" & installed PT welds on 5-1/2" csg to 10 surface. Installed wellhead & 1/12/17, ran 35 jts 2-3/8" 4.7# & rods. Released rig on 1/13	final inspection. IR BAD CSG, RETRIEVE found bad 8-5/8" csg belo d 5-1/2" slip X slip collar in 00 psi-OK. Installed 8-5/8 valves. On 1/10/17, MIR # J-55 & 65 jts 2-7/8" 6.5# /17.	RBP @ 1800', & RETURN TH w csg head. Cut off 8-5/8" csg 5-1/2" csg & stubbed back to 3" slip X slip collar & stubbed b USU. Retrieved RBP @ 1800	HE WELL TO PRODUCTION surface. vack to '& TOH. On 7'. Ran pump	ed and the operator has 3 - 2 - 1 - N 3 - 2 - 1 - N 3 - 2 - 1 - N 5 - 2 - 1 - N	
THIS WORK WAS TO REPA On 12/8/16, dug out cellar & 1 csg. Cut off 5-1/2" & installed PT welds on 5-1/2" csg to 10 surface. Installed wellhead & 1/12/17, ran 35 jts 2-3/8" 4.74 & rods. Released rig on 1/13	final inspection. IR BAD CSG, RETRIEVE found bad 8-5/8" csg belo 5-1/2" slip X slip collar in 00 psi-OK. Installed 8-5/8 valves. On 1/10/17, MIRI 4 J-55 & 65 jts 2-7/8" 6.5# /17. true and correct. Electronic Submission # For LIME ROCK Committed to AFMSS for	RBP @ 1800', & RETURN TH w csg head. Cut off 8-5/8" csg 5-1/2" csg & stubbed back to 3" slip X slip collar & stubbed b USU. Retrieved RBP @ 1800 J-55 tbg. Landed tbg @ 3227 J. M. H.W. 4364160 verified by the BLM Wei RESOURCES I-A, L.P., sent to processing by DEBORAH MCKI	HE WELL TO PRODUCTION surface. back to '& TOH. On 7'. Ran pump Approval Fol Constraint information System the Carlsbad INNEY on 01/24/2017 ()	ed and the operator has 3 - 2 - 1 - 1 2 - 1 - 1 2 - 1 - 1 3 - 2 - 1 3 - 2 - 1 - 1 - 1 1 - 1 - 1 1 - 1 - 1 - 1	
THIS WORK WAS TO REPA On 12/8/16, dug out cellar & f csg. Cut off 5-1/2" & installed PT welds on 5-1/2" csg to 10 surface. Installed wellhead & 1/12/17, ran 35 jts 2-3/8" 4.7# & rods. Released rig on 1/13	final inspection. IR BAD CSG, RETRIEVE found bad 8-5/8" csg belo 5-1/2" slip X slip collar in 00 psi-OK. Installed 8-5/8 valves. On 1/10/17, MIRI 4 J-55 & 65 jts 2-7/8" 6.5# /17. true and correct. Electronic Submission # For LIME ROCK Committed to AFMSS for	RBP @ 1800', & RETURN TH w csg head. Cut off 8-5/8" csg 5-1/2" csg & stubbed back to 3" slip X slip collar & stubbed b USU. Retrieved RBP @ 1800 J-55 tbg. Landed tbg @ 3227 J. M. H.W. 4364160 verified by the BLM Wei RESOURCES I-A, L.P., sent to processing by DEBORAH MCKI	HE WELL TO PRODUCTION g below bad surface. back to '& TOH. On 7'. Ran pump Approval Fol Minformation System the Carlsbad	ed and the operator has 3 - 2 - 1 - 1 2 - 1 - 1 2 - 1 - 1 3 - 2 - 1 3 - 2 - 1 - 1 - 1 1 - 1 - 1 1 - 1 - 1 - 1	
THIS WORK WAS TO REPA On 12/8/16, dug out cellar & 1 csg. Cut off 5-1/2" & installed PT welds on 5-1/2" csg to 10 surface. Installed wellhead & 1/12/17, ran 35 jts 2-3/8" 4.7# & rods. Released rig on 1/13 Dock Wood	final inspection. IR BAD CSG, RETRIEVE found bad 8-5/8" csg belo 5-1/2" slip X slip collar in 00 psi-OK. Installed 8-5/8 valves. On 1/10/17, MIRI 4 J-55 & 65 jts 2-7/8" 6.5# /17. true and correct. Electronic Submission # For LIME ROCK Committed to AFMSS for	RBP @ 1800', & RETURN TH w csg head. Cut off 8-5/8" csg 5-1/2" csg & stubbed back to " slip X slip collar & stubbed b USU. Retrieved RBP @ 1800 J-55 tbg. Landed tbg @ 3227 J. M. hwl MAR hwl RESOURCES I-A, L.P., sent to processing by DEBORAH MCKI Title PETRO	HE WELL TO PRODUCTION surface. back to '& TOH. On 7'. Ran pump Approval Fol Constraint information System the Carlsbad INNEY on 01/24/2017 ()	ed and the operator has 3-2-7-17 Epired for record - N 5- NEPRID DIL CONSER MAR 2 7 20 RECEIVER	
THIS WORK WAS TO REPA On 12/8/16, dug out cellar & 1 csg. Cut off 5-1/2" & installed PT welds on 5-1/2" csg to 10 surface. Installed wellhead & 1/12/17, ran 35 jts 2-3/8" 4.74 & rods. Released rig on 1/13	final inspection. IR BAD CSG, RETRIEVE found bad 8-5/8" csg belo 5-1/2" slip X slip collar in 00 psi-OK. Installed 8-5/8 valves. On 1/10/17, MIR 4 J-55 & 65 jts 2-7/8" 6.5# /17. IMARY PPDVA is true and correct. Electronic Submission # For LIME ROCK Committed to AFMSS for PPIN Submission)	RBP @ 1800', & RETURN TH w csg head. Cut off 8-5/8" csg 5-1/2" csg & stubbed back to " slip X slip collar & stubbed b USU. Retrieved RBP @ 1800 J-55 tbg. Landed tbg @ 3227 J. M. hwl MAR hwl RESOURCES I-A, L.P., sent to processing by DEBORAH MCKI Title PETRO	HE WELL TO PRODUCTION g below bad surface. hack to ' & TOH. On ''. Ran pump Approval for Co with information System the Carlsbad INNEY on 01/24/2017 () ILEUMENGNEER ACCEPTED FOR R	ed and the operator has 3-2-7-17 Epired for record - N 5- NEPRID DIL CONSER MAR 2 7 20 RECEIVER	
THIS WORK WAS TO REPA On 12/8/16, dug out cellar & f csg. Cut off 5-1/2" & installed PT welds on 5-1/2" csg to 10 surface. Installed wellhead & 1/12/17, ran 35 jts 2-3/8" 4.7# & rods. Released rig on 1/13 DOL W/de 14. I hereby certify that the foregoing in Name (Printed/Typed) MIKE PII Signature (Electronic	final inspection. IR BAD CSG, RETRIEVE found bad 8-5/8" csg belo d 5-1/2" slip X slip collar in 00 psi-OK. Installed 8-5/8 valves. On 1/10/17, MIRI # J-55 & 65 jts 2-7/8" 6.5# /17. IMEROVA is true and correct. Electronic Submission # For LIME ROCK Committed to AFMSS for PPIN Submission) THIS SPACE FO	RBP @ 1800', & RETURN TH w csg head. Cut off 8-5/8" csg 5-1/2" csg & stubbed back to "slip X slip collar & stubbed b USU. Retrieved RBP @ 1800 J-55 tbg. Landed tbg @ 3227 L. MAA have "364160 verified by the BLM Wel RESOURCES I-A, L.P., sent to processing by DEBORAH MCKI Title PETRO Date 01/18/2 DR FEDERAL OR STATE	HE WELL TO PRODUCTION g below bad surface. hack to ' & TOH. On ''. Ran pump Approval for Co with information System the Carlsbad INNEY on 01/24/2017 () ILEUMENGNEER ACCEPTED FOR R	ed and the operator has 3 - 2 - 1 - 2 Equed for record - N - 1 OIL CONSER MAR 2 7 20 RECEIVED ECORD	
THIS WORK WAS TO REPA On 12/8/16, dug out cellar & f csg. Cut off 5-1/2" & installed PT welds on 5-1/2" csg to 10 surface. Installed wellhead & 1/12/17, ran 35 jts 2-3/8" 4.7# & rods. Released rig on 1/13 DOC W/de 14. 1 hereby certify that the foregoing in Name (Printed/Typed) MIKE PII Signature (Electronic Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to cond	final inspection. IR BAD CSG, RETRIEVE found bad 8-5/8" csg belo 1 5-1/2" slip X slip collar in 00 psi-OK. Installed 8-5/8 valves. On 1/10/17, MIRI # J-55 & 65 jts 2-7/8" 6.5# /17. IME PPTOVO is true and correct. Electronic Submission # For LIME ROCK Committed to AFMSS for PPIN Submission) THIS SPACE FO ed. Approval of this notice does putable title to those rights in the uct operations thereon.	RBP @ 1800', & RETURN TH w csg head. Cut off 8-5/8" csg a 5-1/2" csg & stubbed back to "slip X slip collar & stubbed b USU. Retrieved RBP @ 1800 J-55 tbg. Landed tbg @ 3227	HE WELL TO PRODUCTION g below bad surface. hack to '& TOH. On ''. Ran pump APPYDUAL OC CARLSBAD SUREAU OF LAND MAYOR CARLSBAD FUR DATA	ed and the operator has 3 - 2 - 1 - 2 Equed for record - N 5 - OPEID DIL GONSER MAR 2 7 20 ECENTER ECORD	
THIS WORK WAS TO REPA On 12/8/16, dug out cellar & f csg. Cut off 5-1/2" & installed PT welds on 5-1/2" csg to 10 surface. Installed wellhead & 1/12/17, ran 35 jts 2-3/8" 4.7f & rods. Released rig on 1/13 Dock Wdw 14. I hereby certify that the foregoing in Name (Printed/Typed) MIKE PII Signature (Electronic	final inspection. IR BAD CSG, RETRIEVE found bad 8-5/8" csg belo 1 5-1/2" slip X slip collar in 00 psi-OK. Installed 8-5/8 valves. On 1/10/17, MIRI # J-55 & 65 jts 2-7/8" 6.5# /17. IME PPTOVO s true and correct. Electronic Submission # For LIME ROCK Committed to AFMSS for PPIN Submission) THIS SPACE FO ed. Approval of this notice does putable title to those rights in the uct operations thereon. U.S.C. Section 1212, make it a	RBP @ 1800', & RETURN TH w csg head. Cut off 8-5/8" csg a 5-1/2" csg & stubbed back to "slip X slip collar & stubbed b USU. Retrieved RBP @ 1800 J-55 tbg. Landed tbg @ 3227 L. M.H. M.H. B. M.H. M.H. D. M.H. M.H. D. M.H. M.H. D. M.	HE WELL TO PRODUCTION g below bad surface. hack to '& TOH. On ''. Ran pump APPYDUAL OC CARLSBAD SUREAU OF LAND MAYOR CARLSBAD FUR DATA	ed and the operator has 3 - 2 - 1 - N Equed for record - N 1 DIL GONSER MAR 2 7 201 RECEIVER ECORD Date MAR 2 MAR	