## **NM OIL CONSERVATION**

ARTESIA DISTRICT

JUL 0 3 2017

Submit One Copy To Appropriate District State o	of New Me	xico	Form C-103
Office Energy, Minera	ls and Natu		Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240			WELL AFT NO.
District II 311 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		DIVISION -	30-015-31338 5. Indicate Type of Lease
istrict III 1220 South St. Francis Dr.		icis Dr.	STATE STATE
00 Rio Brazos Rd., Aztec, NM 87410 strict IV Santa Fe, NM 87505		/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		JG BACK TO A	Scary Creek 25A St Com
PROPOSALS.) 1. Type of Well: Oil Well 🔀 Gas Well Other			8. Well Number 1
2. Name of Operator			9. OGRID Number
DEVON ENERGY PRODUCTION CO LP			6137
3. Address of Operator			10. Pool name or Wildcat
PO BOX 250, ARTESIA, NM 88211			WC Scary Creek; Atoka (Gas)
4. Well Location			
Unit Letter A : 660 feet from the North line and 660 feet from the East line			
Section 25 Township 20S Range 26E NMPM County Eddy			
11. Elevation (Show		,	
3281' KB; 3264' GL;			
12. Check Appropriate Box to Indicate Nature of	i notice, R	eport or Other Da	ta
NOTICE OF INTENTION TO:		SUBS	EQUENT REPORT OF:
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDO	ON 🗌	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON 🔲 CHANGE PLANS		COMMENCE DRIL	LING OPNS. 🔲 PAND A 🔄
PULL OR ALTER CASING 🛛 MULTIPLE COMPL		CASING/CEMENT	JOB 🗍
OTHER:		Location is real	idy for OCD inspection after P&A
All pits have been remediated in compliance with OCI		he terms of the Opera	tor's pit permit and closure plan.
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cather</li> </ul>	odic protecti	he terms of the Opera on holes have been p	tor's pit permit and closure plan. roperly abandoned.
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cather</li> <li>A steel marker at least 4" in diameter and at least 4' about the statement of the statement of</li></ul>	odic protecti	he terms of the Opera on holes have been p level has been set in c	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL M</li> </ul>	odic protecti bove ground NUMBER, A	he terms of the Opera on holes have been p level has been set in o <b>API NUMBER, QU</b> A	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <b>ARTER/QUARTER LOCATION OR</b>
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, AND</li> </ul>	odic protecti ove ground NUMBER, A D RANGE.	he terms of the Opera on holes have been pr level has been set in o <b>API NUMBER, OUA</b> All INFORMATION	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <b>ATTER/QUARTER LOCATION OR</b> N HAS BEEN WELDED OR
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> </ul>	odic protecti pove ground NUMBER, A D RANGE. KER'S SUR	the terms of the Opera on holes have been pr level has been set in or <b>API NUMBER, QUA</b> All INFORMATION FACE. 32.5498543	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <b>ARTER/QUARTER LOCATION OR</b> N HAS BEEN WELDED OR , -104.3311615
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to a</li> </ul>	odic protecti pove ground NUMBER, A D RANGE. KER'S SUR	the terms of the Opera on holes have been pr level has been set in or <b>API NUMBER, QUA</b> All INFORMATION FACE. 32.5498543	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <b>ARTER/QUARTER LOCATION OR</b> N HAS BEEN WELDED OR , -104.3311615
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to o other production equipment.</li> </ul>	odic protecti pove ground i <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SUR</u> original grou	the terms of the Opera on holes have been pr level has been set in or <b>API NUMBER, QUA</b> All INFORMATION FACE. 32.5498543 nd contour and has b	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <b>ARTER/QUARTER LOCATION OR</b> N HAS BEEN WELDED OR , -104.3311615 een cleared of all junk, trash, flow lines and
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>X The location has been leveled as nearly as possible to o other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been curved.</li> </ul>	odic protecti pove ground i <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SUR</u> original grou tt off at least	the terms of the Opera on holes have been pro- level has been set in or <u>API NUMBER, QUA</u> <u>All INFORMATION</u> <u>FACE</u> . 32.5498543 and contour and has be two feet below groun	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <b>ARTER/QUARTER LOCATION OR</b> <b>N HAS BEEN WELDED OR</b> , -104.3311615 een cleared of all junk, trash, flow lines and d level.
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to o other production equipment.</li> </ul>	odic protecti pove ground <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SUR</u> original grou at off at least se, the batter	he terms of the Opera on holes have been pr level has been set in or <u>AII INFORMATION FACE.</u> 32.5498543 nd contour and has b two feet below groun y and pit location(s) l	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <b>ARTER/QUARTER LOCATION OR</b> <b>N HAS BEEN WELDED OR</b> <b>, -104.3311615</b> een cleared of all junk, trash, flow lines and d level. have been remediated in compliance with
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to a other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cu</li> <li>If this is a one-well lease or last remaining well on lease OCD rules and the terms of the Operator's pit permit and cu from lease and well location.</li> </ul>	odic protecti bove ground i <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SUR</u> original grou at off at least se, the batter losure plan.	he terms of the Opera on holes have been pr level has been set in or <u>API NUMBER, OUA</u> <u>All INFORMATION</u> <u>FACE.</u> 32.5498543 nd contour and has b two feet below groun y and pit location(s) I All flow lines, produ	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <u>ARTER/QUARTER LOCATION OR</u> <u>N HAS BEEN WELDED OR</u> , -104.3311615 een cleared of all junk, trash, flow lines and d level. have been remediated in compliance with ction equipment and junk have been removed
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to a other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cur</li> <li>If this is a one-well lease or last remaining well on leas</li> <li>OCD rules and the terms of the Operator's pit permit and clifton lease and well location.</li> <li>All metal bolts and other materials have been removed.</li> </ul>	odic protecti bove ground i <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SUR</u> original grou at off at least se, the batter losure plan.	he terms of the Opera on holes have been pr level has been set in or <u>API NUMBER, OUA</u> <u>All INFORMATION</u> <u>FACE.</u> 32.5498543 nd contour and has b two feet below groun y and pit location(s) I All flow lines, produ	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <u>ARTER/QUARTER LOCATION OR</u> <u>N HAS BEEN WELDED OR</u> , -104.3311615 een cleared of all junk, trash, flow lines and d level. have been remediated in compliance with ction equipment and junk have been removed
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to a other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cut</li> <li>If this is a one-well lease or last remaining well on leas</li> <li>OCD rules and the terms of the Operator's pit permit and clifton lease and well location.</li> <li>All metal bolts and other materials have been removed.</li> </ul>	odic protecti bove ground i <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SUR</u> original grou tt off at least se, the batter losure plan. . Portable ba	he terms of the Opera on holes have been pr level has been set in or <u>API NUMBER, QUA</u> <u>All INFORMATION</u> <u>FACE.</u> 32.5498543 nd contour and has b two feet below groun y and pit location(s) I All flow lines, produ	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <u>ARTER/QUARTER LOCATION OR</u> <u>N HAS BEEN WELDED OR</u> , -104.3311615 een cleared of all junk, trash, flow lines and d level. have been remediated in compliance with ction equipment and junk have been removed
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to a other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cut</li> <li>If this is a one-well lease or last remaining well on leas</li> <li>OCD rules and the terms of the Operator's pit permit and clifton lease and well location.</li> <li>All metal bolts and other materials have been removed.</li> <li>All other environmental concerns have been addressed</li> </ul>	odic protecti bove ground i <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SUR</u> original grou t off at least se, the batter losure plan. . Portable ba d as per OCE	he terms of the Opera on holes have been pr level has been set in of <u>AII INFORMATION</u> FACE. 32.5498543 nd contour and has b two feet below groun y and pit location(s) I All flow lines, produ uses have been remov D rules.	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <b>ARTER/QUARTER LOCATION OR</b> <b>N HAS BEEN WELDED OR</b> <b>, -104.3311615</b> een cleared of all junk, trash, flow lines and d level. have been remediated in compliance with ction equipment and junk have been removed ed. (Poured onsite concrete bases do not have
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to a other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cut</li> <li>If this is a one-well lease or last remaining well on leas</li> <li>OCD rules and the terms of the Operator's pit permit and clifton lease and well location.</li> <li>All metal bolts and other materials have been removed.</li> </ul>	odic protecti bove ground i <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SUR</u> original grou t off at least se, the batter losure plan. . Portable ba d as per OCE	he terms of the Opera on holes have been pr level has been set in of <u>AII INFORMATION</u> FACE. 32.5498543 nd contour and has b two feet below groun y and pit location(s) I All flow lines, produ uses have been remov D rules.	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <b>ARTER/QUARTER LOCATION OR</b> <b>N HAS BEEN WELDED OR</b> <b>, -104.3311615</b> een cleared of all junk, trash, flow lines and d level. have been remediated in compliance with ction equipment and junk have been removed ed. (Poured onsite concrete bases do not have
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to a other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cu</li> <li>If this is a one-well lease or last remaining well on lease OCD rules and the terms of the Operator's pit permit and cl from lease and well location.</li> <li>All metal bolts and other materials have been removed.</li> <li>All other environmental concerns have been addressed</li> <li>Pipelines and flow lines have been abandoned in according the state of the location is a one-well lease or last remaining well on lease</li> </ul>	odic protecti bove ground i NUMBER, <u>A</u> D RANGE. KER'S SUR original grou tt off at least se, the batter losure plan. . Portable ba d as per OCE rdance with 1	he terms of the Opera on holes have been pr level has been set in or <u>API NUMBER, QUA</u> <u>All INFORMATION</u> <u>FACE.</u> 32.5498543 nd contour and has b two feet below groun y and pit location(s) I All flow lines, produ uses have been remov D rules. 19.15.35.10 NMAC.	ttor's pit permit and closure plan. roperly abandoned. concrete. It shows the <u>ARTER/QUARTER LOCATION OR</u> <u>N HAS BEEN WELDED OR</u> , -104.3311615 een cleared of all junk, trash, flow lines and d level. have been remediated in compliance with ction equipment and junk have been removed ed. (Poured onsite concrete bases do not have All fluids have been removed from non-
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to a other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cu</li> <li>If this is a one-well lease or last remaining well on lease OCD rules and the terms of the Operator's pit permit and cl from lease and well location.</li> <li>All metal bolts and other materials have been removed.</li> <li>to be removed.)</li> <li>All other environmental concerns have been addressed</li> <li>Pipelines and flow lines have been abandoned in accorretrieved flow lines and pipelines.</li> <li>If this is a one-well lease or last remaining well on lease location, except for utility's distribution infrastructure.</li> </ul>	odic protecti pove ground i <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SUR</u> original grou it off at least se, the batter dosure plan. . Portable ba d as per OCE rdance with i use: all electri	he terms of the Opera on holes have been pr level has been set in or <u>API NUMBER, QUA</u> <u>All INFORMATION</u> <u>FACE.</u> 32.5498543 nd contour and has b two feet below groun y and pit location(s) I All flow lines, produ uses have been remov O rules. [9.15.35.10 NMAC. cal service poles and	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <u>ARTER/QUARTER LOCATION OR</u> <u>N HAS BEEN WELDED OR</u> , -104.3311615 een cleared of all junk, trash, flow lines and d level. have been remediated in compliance with ction equipment and junk have been removed ed. (Poured onsite concrete bases do not have All fluids have been removed from non- lines have been removed from lease and well
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to a other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cu</li> <li>If this is a one-well lease or last remaining well on lease OCD rules and the terms of the Operator's pit permit and cl from lease and well location.</li> <li>All metal bolts and other materials have been removed.</li> <li>All other environmental concerns have been addressed</li> <li>Pipelines and flow lines have been abandoned in according the state of the location is a one-well lease or last remaining well on lease</li> </ul>	odic protecti pove ground i <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SUR</u> original grou it off at least se, the batter dosure plan. . Portable ba d as per OCE rdance with i use: all electri	he terms of the Opera on holes have been pr level has been set in or <u>API NUMBER, QUA</u> <u>All INFORMATION</u> <u>FACE.</u> 32.5498543 nd contour and has b two feet below groun y and pit location(s) I All flow lines, produ uses have been remov O rules. [9.15.35.10 NMAC. cal service poles and	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <u>ARTER/QUARTER LOCATION OR</u> <u>N HAS BEEN WELDED OR</u> , -104.3311615 een cleared of all junk, trash, flow lines and d level. have been remediated in compliance with ction equipment and junk have been removed ed. (Poured onsite concrete bases do not have All fluids have been removed from non- lines have been removed from lease and well
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to a other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cut</li> <li>If this is a one-well lease or last remaining well on least OCD rules and the terms of the Operator's pit permit and cl from lease and well location.</li> <li>All metal bolts and other materials have been removed.</li> <li>to be removed.)</li> <li>All other environmental concerns have been addressed</li> <li>Pipelines and flow lines have been abandoned in accord retrieved flow lines and pipelines.</li> <li>If this is a one-well lease or last remaining well on least to be removed.</li> <li>All other environmental concerns have been addressed</li> <li>Pipelines and pipelines.</li> <li>If this is a one-well lease or last remaining well on least to be removed.</li> </ul>	odic protecti bove ground i <b>NUMBER, A</b> <b>D RANGE.</b> <b>KER'S SUR</b> original grou it off at least i se, the batter ilosure plan. . Portable ba d as per OCE rdance with i ase: all electri appropriate l	he terms of the Opera on holes have been pr level has been set in of <u>AII INFORMATION</u> <u>FACE.</u> 32.5498543 nd contour and has b two feet below groun y and pit location(s) I All flow lines, produ uses have been remov O rules. 19.15.35.10 NMAC. cal service poles and District office to sche	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <u>ARTER/QUARTER LOCATION OR</u> <u>N HAS BEEN WELDED OR</u> , -104.3311615 een cleared of all junk, trash, flow lines and d level. have been remediated in compliance with ction equipment and junk have been removed ed. (Poured onsite concrete bases do not have All fluids have been removed from non- lines have been removed from lease and well
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to a other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cur</li> <li>If this is a one-well lease or last remaining well on leas</li> <li>OCD rules and the terms of the Operator's pit permit and clifton lease and well location.</li> <li>All metal bolts and other materials have been removed.</li> <li>All other environmental concerns have been addressed</li> <li>Pipelines and flow lines have been abandoned in accorretrieved flow lines and pipelines.</li> <li>If this is a one-well lease or last remaining well on lease location, except for utility's distribution infrastructure.</li> <li>When all work has been completed, return this form to the SIGNATURE August 2000 and a statement of the s</li></ul>	Addic protecti Dove ground i NUMBER, A D RANGE. KER'S SUR original grou at off at least se, the batter dosure plan. Portable ba d as per OCE rdance with i appropriate i 	he terms of the Opera on holes have been pr level has been set in or <u>AII INFORMATION FACE</u> . 32.5498543 nd contour and has b two feet below groun y and pit location(s) I All flow lines, produ uses have been remov O rules. 19.15.35.10 NMAC. cal service poles and District office to sche ADMIN FIELD SUP	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <b>ARTER/OUARTER LOCATION OR</b> <b>N HAS BEEN WELDED OR</b> <b>, -104.3311615</b> een cleared of all junk, trash, flow lines and d level. have been remediated in compliance with ction equipment and junk have been removed ed. (Poured onsite concrete bases do not have All fluids have been removed from non- lines have been removed from lease and well dule an inspection. PORTDATE6/29/2017
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to a other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cu</li> <li>If this is a one-well lease or last remaining well on lease OCD rules and the terms of the Operator's pit permit and ci from lease and well location.</li> <li>All metal bolts and other materials have been removed.</li> <li>All other environmental concerns have been addressed</li> <li>Pipelines and flow lines have been abandoned in accorretrieved flow lines and pipelines.</li> <li>If this is a one-well lease or last remaining well on lease location, except for utility's distribution infrastructure.</li> <li>When all work has been completed, return this form to the SIGNATURE August August</li></ul>	Addic protecti Dove ground i NUMBER, A D RANGE. KER'S SUR original grou at off at least se, the batter dosure plan. Portable ba d as per OCE rdance with i appropriate i 	he terms of the Opera on holes have been pr level has been set in or <u>AII INFORMATION FACE</u> . 32.5498543 nd contour and has b two feet below groun y and pit location(s) I All flow lines, produ uses have been remov O rules. 19.15.35.10 NMAC. cal service poles and District office to sche ADMIN FIELD SUP	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <b>ARTER/OUARTER LOCATION OR</b> <b>N HAS BEEN WELDED OR</b> <b>, -104.3311615</b> een cleared of all junk, trash, flow lines and d level. have been remediated in compliance with ction equipment and junk have been removed ed. (Poured onsite concrete bases do not have All fluids have been removed from non- lines have been removed from lease and well dule an inspection. PORTDATE6/29/2017
<ul> <li>All pits have been remediated in compliance with OCI</li> <li>Rat hole and cellar have been filled and leveled. Cath</li> <li>A steel marker at least 4" in diameter and at least 4' ab</li> <li>OPERATOR NAME, LEASE NAME, WELL N</li> <li>UNIT LETTER, SECTION, TOWNSHIP, ANI</li> <li>PERMANENTLY STAMPED ON THE MARK</li> <li>The location has been leveled as nearly as possible to a other production equipment.</li> <li>Anchors, dead men, tie downs and risers have been cut</li> <li>If this is a one-well lease or last remaining well on least OCD rules and the terms of the Operator's pit permit and cl from lease and well location.</li> <li>All metal bolts and other materials have been removed.</li> <li>All other environmental concerns have been addressed</li> <li>Pipelines and flow lines have been abandoned in accorretrieved flow lines and pipelines.</li> <li>If this is a one-well lease or last remaining well on least observed.</li> <li>If this is a one-well lease or last remaining well on least observed.</li> <li>All other environmental concerns have been addressed</li> <li>Pipelines and flow lines have been abandoned in accorretrieved flow lines and pipelines.</li> <li>If this is a one-well lease or last remaining well on least location, except for utility's distribution infrastructure.</li> <li>When all work has been completed, return this form to the SIGNATURE August Au</li></ul>	odic protecti Dove ground i NUMBER, A D RANGE. KER'S SUR original grou t off at least se, the batter losure plan. . Portable ba d as per OCE rdance with i use: all electri appropriate i TITLEA 	he terms of the Opera on holes have been pr level has been set in or <u>All INFORMATION FACE</u> . 32.5498543 nd contour and has b two feet below groun y and pit location(s) I All flow lines, produ uses have been remov O rules. 19.15.35.10 NMAC. cal service poles and District office to sche ADMIN FIELD SUP houd@dvn.com _ P	tor's pit permit and closure plan. roperly abandoned. concrete. It shows the <b>ARTER/OUARTER LOCATION OR</b> <b>N HAS BEEN WELDED OR</b> <b>, -104.3311615</b> een cleared of all junk, trash, flow lines and d level. have been remediated in compliance with ction equipment and junk have been removed ed. (Poured onsite concrete bases do not have All fluids have been removed from non- lines have been removed from lease and well dule an inspection. PORTDATE6/29/2017

Conditions of Approval (if any):

•