

State of New Mexico

Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

David Catanach
Division Director



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

05-Dec-17

BTA OIL PRODUCERS, LLC
104 S. Pecos
Midland TX 79701-9701

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
PARDUE B 8808 JVP No.001						
12/05/2017	Routine/Periodic	Tony Morales	Yes	No	3/10/2018	iTM1733944857
Violations General Housekeeping (Rule 114)						
Comments on Inspection: OK. All Equipment and Location in Good Shape. HEAD 19.15.10.8 PJO. STAINING AROUND WELL						
PARDUE B 8808 JVP No.002						
12/05/2017	Routine/Periodic	Tony Morales	Yes	No	3/10/2018	iTM1733943571
Violations General Housekeeping (Rule 114)						
Comments on Inspection: OK. All Equipment and Location in Good Shape. HEAD 19.15.10.8 PJO. STAINING AROUND WELL						

PARDUE C 8808 JVP No.001Y N-11-23S-28E 30-015-26583-00-00
 Inspection Date: 12/05/2017
 Type Inspection: Routine/Periodic
 Inspector: Tony Morales
 Violation?: Yes
 *Significant Non-Compliance?: No
 Corrective Action Due By: 3/10/2018
 Inspection No.: iTM1733949108
 Violations: General Housekeeping (Rule 114)
 Comments on Inspection: OK. All Equipment and Location in Good Shape. HEAD 19.15.10.5 PJO. STAINING AROUND WELL

PARDUE B 8808 JVP No.003 K-11-23S-28E 30-015-32493-00-00
 Inspection Date: 12/05/2017
 Type Inspection: Routine/Periodic
 Inspector: Tony Morales
 Violation?: Yes
 *Significant Non-Compliance?: No
 Corrective Action Due By: 3/10/2018
 Inspection No.: iTM1733945046
 Violations: Absent Well Identification Signs (Rule 103)
 General Housekeeping (Rule 114)
 Comments on Inspection: OK. All Equipment and Location in Good Shape. HEAD 19.15.10.8 LOCATION SIGN NOT VISIBLE 19.15.16.8 PJO. STAINING AROUND WELL

PARDUE C 8808 JVP No.003 N-11-23S-28E 30-015-32671-00-00
 Inspection Date: 12/05/2017
 Type Inspection: Routine/Periodic
 Inspector: Tony Morales
 Violation?: Yes
 *Significant Non-Compliance?: No
 Corrective Action Due By: 3/10/2018
 Inspection No.: iTM1733949023
 Violations: General Housekeeping (Rule 114)
 Comments on Inspection: OK. All Equipment and Location in Good Shape. HEAD 19.15.10.5 PJO. STAINING AROUND WELL

PARDUE B 8808 JVP No.004 K-11-23S-28E 30-015-33638-00-00
 Inspection Date: 12/05/2017
 Type Inspection: Routine/Periodic
 Inspector: Tony Morales
 Violation?: Yes
 *Significant Non-Compliance?: No
 Corrective Action Due By: 3/10/2018
 Inspection No.: iTM1733943859
 Violations: General Housekeeping (Rule 114)
 Comments on Inspection: OK. All Equipment and Location in Good Shape. OLD TUBING ON LOCATION 19.15.10.8 PJ. STAINING AROUND WELL HEAD

PARDUE B 8808 JVP No.005 K-11-23S-28E 30-015-34622-00-00
 Inspection Date: 12/05/2017
 Type Inspection: Routine/Periodic
 Inspector: Tony Morales
 Violation?: Yes
 *Significant Non-Compliance?: No
 Corrective Action Due By: 3/10/2018
 Inspection No.: iTM1733945195
 Violations: General Housekeeping (Rule 114)
 Comments on Inspection: OK. All Equipment and Location in Good Shape. HEAD 19.15.10.8 PJO. STAINING AROUND WELL

PARDUE D 8808 JV-P No.003 E-11-23S-28E 30-015-35870-00-00
 Inspection Date: 12/05/2017
 Type Inspection: Routine/Periodic
 Inspector: Tony Morales
 Violation?: Yes
 *Significant Non-Compliance?: No
 Corrective Action Due By: 3/10/2018
 Inspection No.: iTM1733946111
 Violations: General Housekeeping (Rule 114)
 Comments on Inspection: OK. All Equipment and Location in Good Shape. HEAD 19.15.10.8 PJO. STAINING AROUND WELL

PARDUE B 8808 JVP		No.007	L-11-23S-28E	30-015-38961-00-00
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
12/05/2017	Routine/Periodic	Tony Morales	Yes	No
	Violations			Corrective Action Due By:
	General Housekeeping (Rule 114)			3/10/2018
Comments on Inspection:	OK. All Equipment and Location in Good Shape.		PJO. STAINING AROUND WELL HEAD 19.15.10.8	
				Inspection No.
				iTM1733943122

PARDUE C 8808 JVP		No.005	L-11-23S-28E	30-015-38999-00-00
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
12/05/2017	Routine/Periodic	Tony Morales	Yes	No
	Violations			Corrective Action Due By:
	General Housekeeping (Rule 114)			3/10/2018
Comments on Inspection:	OK. All Equipment an Location in Good Shape.		PJO. STAINING AROUND WELL HEAD TANK ATTERIES OTHER NEED PLACARDS WINDSOCK NEEDS REPLACING 19.15.10.8	
				Inspection No.
				iTM1733943290

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,



Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.
 *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.