

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

oed received
on 2/9/18
District II

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1810727562		OPERATOR		X Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company Vanguard Operating, LLC 258360		Contact Jason Fisher			
Address 5847 San Felipe, STE 3000 Houston, TX 77057		Telephone No. 505-918-0523			
Facility Name Marathon A 25 Battery		Facility Type Tank Battery			
Surface Owner		Mineral Owner State		API No. 3001529966	

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	25	17S	28E	740	North	330	West	Eddy

Latitude 32.8044739 Longitude -104.1861649 NAD83

NATURE OF RELEASE x2=160MCF

Type of Release Gas/Emissions	Volume of Release 80 MCFD	Volume Recovered 0
Source of Release Flare	Date and Hour of Occurrence 2-3-2018	Date and Hour of Discovery N/A
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Amalia Bustamante by email	
By Whom? Chuck Johnston	Date and Hour 7:30 pm 2-3-2018	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Purchaser found leak on their pipeline and requested a volume reduction while making repairs. Gas was sent to flare for two days.		
Describe Area Affected and Cleanup Action Taken.* No impact.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Chuck Johnston		Approved by Environmental Specialist: Accepted for record	
Title: EHS Specialist		Approval Date: 4/13/18	Expiration Date: N/A
E-mail Address: cjohnston@vnrenergy.com		Conditions of Approval: Final	
Date: 2-9-2018 Phone: 432-202-4771		Attached <input checked="" type="checkbox"/> 2AP-4702	

* Attach Additional Sheets If Necessary

4/12/18 AB