## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen

Cabinet Secretary

Matthias Sayer

**Deputy Cabinet Secretary** 

Heather Riley
Division Director



## \*Response Required - Deadline Enclosed\*

Field Inspection Program
"Preserving the Integrity of Our Environment"

03-Jul-18

## **BURNETT OIL CO INC**

Burnett Plaza, Suite 1500 801 Cherry St., Unit 9 Fort Worth TX 76102-6102

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

			INSPECTIO	N DETAIL	SECTION		
GRAYBUR Inspection Date 07/03/2018	G JACKSON  Type Inspection  Routine/Perio		Inspector Tony Morales	Violation? Yes	I-12-17S-30E *Significant Non-Compliance? No	30-015-04128-00-0 Corrective Action Due By: 10/6/2018	Inspection No. iTM1818447408
Comments	on Inspection:	OK. All Equipn 19.15.29	•	Good Shape.	PJO. STAINING A	ROUND WELL HEA	D
GISSLER B Inspection Date	No.005  Type Inspection	1	Inspector	Violation?	J-23-17S-30E *Significant Non-Compliance?	30-015-04300-00-0 Corrective Action Due By:	00 Inspection No.
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818431903
Comments	on Inspection:		nent and Location in LLHEAD / LOCAT			GN WORN STAININ	1G
GISSLER B Inspection Date	No.012  Type Inspection	1	Inspector	Violation?	I-23-17S-30E *Significant Non-Compliance?	30-015-04302-00-Corrective Action Due By:	00 Inspection No.
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818432419
Comments	on Inspection:		nent an Location in GN WORN FADED	•	PJO. STAINING AF	ROUND WELL HEAD	<b>)</b> .

JACKSON H	3 No.024				L-24-17S-30E	30-015-04320-00-0	0
Inspection Date	Type Inspection	1	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818432803
Comments o	n Inspection:	OK. All Equipm STAINED ARE	ent and Location in A APPROX 60' SO	Good Shape.	PJ STAINING ARO ST X 5' 19.15.29	OUND WELL HEAD+	
JACKSON E	3	No.034			E-24-17S-30E	30-015-27440-00-0	0
Inspection Date	Type Inspection	ı	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818436033
Comments o	n Inspection:	OK. All Equipm 19.15.29	ent and Location in	Good Shape.	PJ STAINING ARC	OUND WELL HEAD	
GISSLER B Inspection		No.030			G-23-17S-30E *Significant	30-015-27922-00-0 Corrective	0
Date	Type Inspection		Inspector	Violation?	Non-Compliance?	Action Due By:	Inspection No.
07/03/2018	Routine/Perio		Tony Morales	Yes	No	10/6/2018	iTM1818433619
Comments o	n Inspection:	OK. All Equipm 19.15.29	ent and Location in	Good Shape.	PJO STAINING A	ROUND WELLHEAD	
STEVENS A	No.010				L-13-17S-30E	30-015-32793-00-0	0
Inspection Date	Type Inspection	1	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routinc/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818440905
Comments o	n Inspection:	OK. All Equipm 19.15.29	ent and Location in	Good Shape.	PJ. STAINING AR	OUND WELL HEAD	
STEVENS A	No.011				F-13-17S-30E	30-015-33131-00-0	0
Inspection Date	Type Inspection	1	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818444208
Comments o	n Inspection:	OK. All Equipm 19.15.29	ent and Location in	Good Shape.	PJ. STAINING AR	OUND WELLHEAD	
STEVENS A		No.012			N-13-17S-30E	30-015-34225-00-0	0
Inspection Date	Type Inspection	1	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Perio		Tony Morales	Yes	No.	10/6/2018	iTM1818442078
, ,	n Inspection:		•			ROUND WELLHEAD	
JACKSON A	A No.035				G-13-17S-30E	30-015-34502-00-0	0
Inspection Date	Type Inspection	1	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Perio		Tony Morales	Yes	No	10/6/2018	iTM1818445185
	n Inspection:	OK. All Equipm	ent and Location in	Good Shape	PJ. CONTAMIN	IATED MATERIAL O	
JACKSON A	No.027Q				A-13-17S-30E	30-015-34765-00-0	0
Inspection	Type Inspection		Inchester	Violation?	*Significant	Corrective	
Date 07/03/2018	Routine/Perio		Inspector Tony Morales	Yioiation:	Non-Compliance?	Action Due By:	Inspection No.
	n Inspection:		•		. PJ WRONG API O	10/6/2018 ON LOCATION	iTM1818446107
			BE "34765" NOT		16.8		
GISSLER B Inspection					D-24-17S-30E *Significant	30-015-41176-00-0 Corrective	0
Date	Type Inspection		Inspector	Violation?	Non-Compliance?	Action Due By:	Inspection No.
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818437378
	n Inspection:	OK. All Equipm					

GISSLER A Inspection Date	No.043  Type Inspection	ı	Inspector	Violation?	B-23-17S-30E *Significant Non-Compliance?	30-015-41177-00-00 Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818435095
Comments o	n Inspection:	OK. All Equipm 19.15.29	ent and Location in	n Good Shape.	PJO. STAINING A	ROUND WELL HEAD	•
JACKSON A Inspection Date	A No.044  Type Inspection		Inspector	Violation?	P-12-17S-30E *Significant Non-Compliance?	30-015-41539-00-00 Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818446557
Comments o	n Inspection:	OK. All Equipm 19.15.29	ent and Location in	n Good Shape.	PJ STAINING ARG	OUND WELL HEAD.	
GISSLER B Inspection Date	Type Inspection	No.104	Inspector	Violation?	H-23-17S-30E *Significant Non-Compliance?	30-015-41801-00-00 Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818434273
Comments o	n Inspection:	OK. All Equipm 19.15.29	ent and Location in	n Good Shape.	PJO STAINING A	ROUND WELLHEAD	
JACKSON I Inspection Date	B No.070  Type Inspection	1	Inspector	Violation?	F-24-17S-30E *Significant Non-Compliance?	30-015-42043-00-00 Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818443221
Comments o	n Inspection:	OK. All Equipm 19.15.29	ent and Location in	n Good Shape.	PJO STAINING A	ROUND WELLHEAD	
JACKSON A Inspection Date	A Type Inspection	No.050	Inspector	Violation?	P-12-17S-30E *Significant Non-Compliance?	30-015-42212-00-00 Corrective Action Due By:	Inspection No.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Yes

OK. All Equipment and Location in Good Shape. PJO STAINING AROUND WELL HEAD.

No

10/6/2018

iTM1818446991

Tony Morales

Sincerely,

Artesia OCD District Office

07/03/2018 Routine/Periodic

19.15.29

**Comments on Inspection:** 

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.