Submit Gopy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-15-20357
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE X
<u>District IV</u> - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH	Echols Com
1. Type of Well: Oil Well	Gas Well X Other	8. Well Number #1
2. Name of Operator Cimarex Energy Co		9. OGRID Number 215099
3. Address of Operator		10. Pool name or Wildcat
202 S. Cheyenne Ave.	Suite 1000 Midland TX 79701	South Carlsbad, Morrow
4. Well Location		
Unit Letter J	: 1980 feet from the South line and	1980 feet from the East line
Section 12	Township 23S Range 26E	NMPM County
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	c.)
L	3233'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON	· · · · · · · · · · · · · · · · · · ·	RILLING OPNS. P AND A
PULL OR ALTER CASING		NTAOB
DOWNHOLE COMMINGLE	1	Carlsbad Atoka, South (ga
CLOSED-LOOP SYSTEM	_	Plug Back - Aloka X
OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed completion of recompletion.		
Please see attached chronological event and current wellbore schematic.		
riease see attached chronological event and current wendore schematic.		
1 1		
update r	ecards	
upart		iteren
		440
Spud Date:	Rig Release Date:	
Spud Date.	Rig Release Date.	
I hereby certify that the information	n above is true and complete to the best of my knowled	dge and helief
Thereby certify that the information above to true and complete to the best of my knowledge and certify.		
Amith.	hambad	E/11/0010
SIGNATURE AYMANY	rawford TITLE Regulatory Analy	yst DATE 5/11/2018
A (Al C.	rawford E-mail address: acrawford@	
Type of print nume	E-mail address: actawiolug	PHONE:
For State Use Only		
APPROVED BY:	TITLE TAH Mg	DATE 16-11-18
Conditions of Approval (if any):		

Echols Com 1J

Plugback/Recompletion Ops

7/26/17- Set CIBP at 11499 with 15sks cement on top. Tagged TOC @ 11419'. Abandon Morrow.

7/28/2017 to 8/4/2017 Found Hole in casing between 719'-751'. Replace bad casing with new casing . Set RBP 2053' and dump 1 sks sand on top, flushed with 7.9 bbls water. Spear Casing. POH with old 4 ½" casing. RIH with New 4 ½" 13.5# L-80 Casing to top of fish and set @ 813'. RIH w/ on off tool to top of sand 10' above RBP @ 2053'. Washed sand down to RBP and circ sand out of hole. Unset and POH with RBP. Pressure tested casing to 2000 psi. Bad test. Another hole in 4 ½" casing.

8/5/2017 to 8/15/2017- Found Hole in 4 ½" casing between 2909'-2878'. Replace bad casing with new casing. Spear casing. POH @ 7000' with old 4 ½" casing. RIH with New 4 ½" 13.5# L-80 casing to top of fish at 7000'. Mix and pump 1390 sks class C and 60 sks Class H cement. Circ 90 bbls cement. Tagged TOC at 11419'.

8/16/2017- Ran CBL Log from 7500' to surface. Ok. Pressure casing to 5012 psi and held for 30 min. Good Test.

8/16/-2017- Perfed Atoka from 10962'-11048' with 120 shots. Acidized with 851 bbls 20% HCL Acid.

8/19/2017- The Atoka did not produce oil/gas and was deemed uneconomic. Will recomplete Cisco Canyon.

8/24/2017- Set CIBP @ 10922 above Atoka. Mix and Pump 25 sks class H Neat cement. TOC 10553'. Abandon Atoka. Set 2nd CIBP at 10525'.

8/29/2017. Test casing. Would not pressure test.

8/31/2017- Determined casing leak was from 6892'- 7082' casing. Set CBP 7120' to isolate casing leak

9/2/2017 to 10/2/2017- mix and pump 5 bbls well lock. Top of well lock is at 6782' Drill out well lock to 7032'. Test casing to 4800 psi. Bad test. Drill out to 7115' leaving 3' well lock and CBP @ 7120'. Pump 5 more bbls well lock. Top of Well lock at 6776'. Wait 24 hrs and drill out well lock to 7016'. Pressure tested casing to 4100 psi. Bad test. Isolate Casing leak from 3084'-3115'. Set CBP @3180'. Pump 5 bbls well lock. Set Packer at 2287'. Shut down for weekend. Discovered tubing and packer full of well lock. MIRU CT unit and drill out well lock from inside tubing.

10/02/2017 to 10/05/2017- to Attempt to Fish pack Fish Packer. Could not recover. Mill on packer. Packer to Surface.

10/07/2017 to 10/20/2017- Attempt to Mill on tail pipe and well lock made approx. 82' in 13 days.

10/20/2017- Top of fish located at 2381.5' EOT at 2734'. Shut well in pending Plug and abandonment.

