

District II - Artesia

811 S. 1st Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575) 748-9720

RECEIVED

OCT 24 2018

HOT 20000

OCT 22 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

DISTRICT II-ARTESIA O.C.D.

BRADENHEAD TEST REPORT

Ch RECEIVED	Operator Name	API Number
	Property Name	Well No.
State 2		1

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	Line	Feet From	Line	County
	2	19	30	1855	001	660	001	Eddy

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☒ NO ☐	YES ☐ NO ☒	INJ ☒ SWD ☐	OIL ☐ GAS ☐	9-17-18

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure					
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _____
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	If applicable type
Gas or Oil	Y / N	Y / N	Y / N	Y / N	fluid injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Danny Smolik</i>	OIL CONSERVATION DIVISION
Printed name: <i>Danny Smolik</i>	Entered RBDMS
Title: <i>Compliance officer</i>	Re-test
E-mail Address: <i>danny.smolik@state.nm.us</i>	
Date: <i>9-11-18</i>	Phone: <i>575 626-0836</i>
	Witness: