

District II - Artesia

811 S. 1st Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575)-748-9720

RECEIVED

HOBBS OCD

OCT 22 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

OCT 24 2018

DISTRICT II-ARTESIA O.C.D.

BRADENHEAD TEST REPORT

Chevron	Operator Name	API Number
	Property Name	Well No.
Benson Sugar & Water Flood Unit		7

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	NS Line	Feet From	EW Line	County
	26	18	30	1530		940		Eddy

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☒ NO	YES ☒ NO	INJ ☒ SWD	OIL ☒ GAS	9-17-18

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure					
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Daniel</i>	OIL CONSERVATION DIVISION	
Printed name: <i>Dan Smolik</i>	Entered RBDMS	
Title: <i>Compliance officer</i>	Re-test	
E-mail Address: <i>danny.smolik@state.nm.us</i>		
Date: <i>9-17-18</i>	Phone: <i>575-624-0886</i>	
Witness: <i>[Signature]</i>		