

District II - Artesia

811 S. 1st Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575) 748-9720

RECEIVED

State of New Mexico

OCT 24 2018

OCT 22 2018 Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

DISTRICT II-ARTESIA O.C.D.

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron		API Number 3001152764400001	
Property Name Benson Shugart Water Flood Unit		Well No. 6	

7. Surface Location

UL - Lot	Section 26	Township 18	Range 30	Feet from 2254	N/S Line	Feet From 1044	E/W Line	County Eddy
----------	----------------------	-----------------------	--------------------	--------------------------	----------	--------------------------	----------	-----------------------

Well Status

TA'D Well YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	SHUT-IN YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	INJECTOR (INJ) SWD	PRODUCER OIL GAS	DATE 9-17-18
---	---	------------------------------	---------------------	------------------------

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure					
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dan Smolik		OIL CONSERVATION DIVISION	
Printed name: Dan Smolik		Entered RBDMS	
Title: Compliance officer		Re-test	
E-mail Address: danny.smolik@state.nm.us			
Date: 9-17-18	Phone: 575 624-0836		
Witness: [Signature]			