

**State Of New Mexico**  
**Energy, Minerals and Natural Resources Department**

Michelle Lujan Grisham  
Governor  
Sarah Cottrell Propst  
Cabinet Secretary  
Todd Leahy  
Deputy Cabinet Secretary

Gabriel Wade  
Division Director



**"Response Required - Deadline Enclosed"**

*Field Inspection Program*  
*"Preserving the Integrity of Our Environment"*

18-Jan-19

**RKI EXPLORATION & PRODUCTION, LLC**  
3817 NW Expressway  
Suite 950  
Oklahoma City, OK 73112

**LETTER OF VIOLATION - Field Inspection**

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

***INSPECTION DETAIL SECTION***

[30-015-41579] ROSS DRAW UNIT #035

OGRID: 246289

C-22-26S-30E 440 FNL 1960 FWL

Inspection Date	Type Inspection	Inspector	Corrective Action Due By	Inspection No.
1/17/2019	Routine Inspection	[DRS] Danny Smolik	4/17/2019	iDRS191742145

**Violations:**

Rule	Violation	Comment
19.15.10.8 Safety Procedures for Drilling and Production	Substandard Equipment and/or Needs Repair	Well head has leak puddle on ground.

Sincerely,

  
Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.