




Form 3160-5 June 2015) DI B	UNITED STATES Carlsbad Field Office FORM APPROVED DEPARTMENT OF THE INTERIOR OCD AFTESIA 5. Lease Serial No.				04-0137	
SUNDRY	SUNDRY NOTICES AND REPORTS ON WELLS					
	is form for proposals to ell. Use form 3160-3 (API			6. If India	n, Allottee or Trib	be Name
SUBMIT IN	TRIPLICATE - Other inst	tructions on page 2		7. If Unit	or CA/Agreement	, Name and/or No.
1. Type of Well S Oil Well Gas Well Ot	her			8. Well Na VIRGC	ume and No.) 24/23 B2HE FI	ED COM 1H
2. Name of Operator MEWBOURNE OIL COMPAN	JACKIE LATHAN ewbourne.com		9. API Well No. 30-015-44655-00-X1			
3a. Address P O BOX 5270 HOBBS, NM 88241		3b. Phone No. (include are Ph: 575 NRS-ON15 CC	a code) DNSER IA DISTI	VATION SHUG	and Pool or Explo RT	ratory Area
4. Location of Well (Footage, Sec., 1			11. County or Parish, State			
Sec 24 T18S R30E SENE 18 32.735077 N Lat, 103.917496	FEB	FEB 08 2019			EDDY COUNTY, NM	
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NATU	CEIVEI RE OF N	OTICE, REPORT	, OR OTHER	DATA
TYPE OF SUBMISSION		ТҮ	PE OF A	CTION		<u></u>
		Deepen	r	Production (Start/R	lesume) 🗖	Water Shut-Off
□ Notice of Intent	Alter Casing	Hydraulic Fract	-	Reclamation		Well Integrity
Subsequent Report	Casing Repair	New Constructi	on C	Recomplete		Other
Final Abandonment Notice	🗖 Change Plans	Plug and Aband	on E] Temporarily Aband	ion W	Well Spud
	Convert to Injection	Plug Back	C	Water Disposal		
testing has been completed. Final Al determined that the site is ready for f 12/18/18 Spud 17 1/2" hole @ 605'. Ra w/additives. Mixed @ 13.5#/g yd. Displaced w/84 bbls of FW BOPE to 5000# & Annular to 3 10.5 PPG EMW. Drilled out w	inal inspection. In 592' of 13 3/8" 54.5# J5 w/1.74 yd. Tail w/200 sks /. Plug down @ 1:00 PM ′ 3500#. At 9:30 A.M. 12/21	5 ST&C Csg. Cemente Class C w/1% CaCl2. I 12/19/18 Circ 264 sks o	d with 37 Aixed @ f cmt to t	5 sks Class C 14.8#/g w/1.33 he pit Test	·	
Charts & Schematic attached				Acconted	For Rec	ord
Bond on file: NM1693 nationw		Accepted For Record NMOCD 412.19				
					<i>d</i> *	
14. I hereby certify that the foregoing is	true and compat					
	Electronic Submission #4	NE OIL COMPANY, sent	to the Ca	arlsbad		
Name(Printed/Typed) RUBY O C	CABALLERO	Title Rf	GULAT	ORY	- <u>.</u>	
Signature (Electronic S	Submission)	Date 02	/04/2019	· · · · · · · · · · · · · · · · · · ·		
	THIS SPACE FO	R FEDERAL OR ST	ATE OF			
Approved By		」 上 、 し し し し し し し し し し し し し	<u>i</u> fit	UFUN MELL	лш	Date
nditions of approval, if any, are attached	not warrant or	ΓE	C 0 5 2019	/ lonath	on Sheparc	
rtify that the applicant holds legal or equ hich would entitle the applicant to condu	ct operations thereon.	01100		/\$	N OVIICAII	
tify that the applicant holds legal or equich would entitle the applicant to condu le 18 U.S.C. Section 1001 and Title 43 tates any false, fictitious or fraudulent s	USC Section 1212 make it a c	rime for any person knowing	ly and will	fully to make to any der	partment or agenc	






















. . .





	WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS Lovington, NM • 575-386-4540	Pg of	
Company: <u>Mupour</u> Lesse: <u>Virgo 24h3 B2HE Feo</u> Mug Size & Type: 12"	Dete: 12 -200-18 COM J 14 Drilling Contractor: 12112(5 and Drill Pipe Size XT39 Tosta	Take (11	-

Required BOP: ____

^{*}Appropriate Casing Velve Must Be Open During BOP Test *







	REMARKS	HIGH PSI	LOW PSI	TEST LENGTH	ITEMS TESTED	TEBT #
pers	~	ž	250	10	Truck test	
Pess		SK	-	Bump	26,25,6,8	2
PESS		SK	250	10	2618	3
PESS		SK	250	10	45.3.8	
pe ss		SK	250	10	18	5
MSS		Sk	250	10	79	6
post		SK	2.50	10	14	7
Pass	· · · · · · · · · · · · · · · · · · ·	sk	250	10	12,9.8	8
pay		SK	250	10	12,10,7	q
per		SK	250	10	12,11,7	[G
Pସ୍ଟ୍ର		3500	250	10	15.11.7	11
Pass		SK	250	10	20,21,22,23,24	12
PUS	· - · · · · · · · · · · · · · · · · · ·	SK	230	10	16	13
PESS		SK	ZSO	10	17	14
Pess Pass		SK	250	10	1311.345	
pass		SK	250	10	12,11,7 UBA	16
					····· ··· ··· ··· ··· ··· ··· ··· ···	
					· · · · · · · · · · · · · · · · · · ·	

* Check Valve Must Be Open/Disebled To Test Kill Line Valves *

Installed BOP:____

FIDING	SERVICE
MANWELDING	-CES, D.
Mrs	· · · · ·

Company Meuboure	Date 12-2018
Lease Virgo Z423BEFeder	
Drilling Contractor Detters on 250	Plug & Drill Pipe Size 2" *139
Accumulator Pressure: 3000 Ma	inifold Pressure: Annular Pressure:
	Function Test - OO&GO#2
To Check - USABLE FLUID IN THE NIT	ROGEN BOTTLES (III.A.2.c.i. or ii or iii)
 Make sure all rams and annular are op 	

- Ensure accumulator is pumped up to working pressure! (Shut off all pumps)
 - 1. Open HCR Valve. (If applicable)
 - 2. Close annular.
 - 3. Close all pipe rams.
 - 4. Open one set of the pipe rams to simulate closing the blind ram.
 - 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).
 - 6. Record remaining pressure 100 psi. Test Fails if pressure is lower than required.
 - a. (950 psi for a 1500 psi system) b. (1200 psi for a 2000 & 3000 psi system)
 - 7. If annular is closed, open it at this time and close HCR.

To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure: a. [800 psi for a 1500 psi system] b. [1100 psi for 2000 and 3000 psi system]
 - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
 - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
 - 3. Record pressure drop 1,000 psi. Test fails if pressure drops below minimum.
- Minimum: a. [700 psi for a 1500 psi system] b. [900 psi for a 2000 & 3000 psi system]

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off value to the tank, {manifold psi should go to 0 psi} close bleed value. Ð
 - 1. Open the HCR valve, {if applicable}
 - 2. Close annular
 - 3. With pumps only, time how long it takes to regain the required manifold pressure.
 - 4. Record elapsed time _______ Test fails if it takes over 2 minutes.
 - a. (950 psi for a 1500 psi system) b. (1200 psi for a 2000 & 3000 psi system)