

Submit One Copy To Appropriate District Office

State of New Mexico

Form C-103

District I

RECEIVED

Energy, Minerals and Natural Resources

Revised November 3, 2011

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

MAR 18 2019

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

DISTRICT II-ARTESIA O.C.D.

WELL API NO.
30-015-21398

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
SRO SWD

8. Well Number
102

9. OGRID Number
229137

10. Pool name or Wildcat
SWD; Devonian

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
COG Operating LLC

3. Address of Operator
2208 W Main Artesia NM 88210

4. Well Location
Unit Letter G : 1980 feet from the North line and 1980 feet from the East line
Section 16 Township 26S Range 28E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3,024 GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- PLUG AND ABANDON
- TEMPORARILY ABANDON
- CHANGE PLANS
- PULL OR ALTER CASING
- MULTIPLE COMPL

SUBSEQUENT REPORT OF:

- REMEDIAL WORK
- ALTERING CASING
- COMMENCE DRILLING OPNS.
- P AND A
- CASING/CEMENT JOB

OTHER:


Location is ready for OCD inspection after P&A

- All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. *Remove - Chemical Tanks - Well head - Buried Power Lines*
 - Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
 - If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. *Remove - Concrete, Tanks, Plastic Lined Trash in Pasture*
 - All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
 - All other environmental concerns have been addressed as per OCD rules.
 - Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.
 - If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.
- Please see attached

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE  TITLE Regulatory Technician

DATE 3/18/2019

TYPE OR PRINT NAME Delilah Flores

E-MAIL: dflores2@concho.com

PHONE: 575-748-6946

For State Use Only

APPROVED BY:

DENIED

TITLE

DENIED

DATE 3/21/19

Conditions of Approval (if any):

SRO 102 SWD
(formerly Hamon St LG-1175 No.1)
1980' fnl, 1980' fel
G-16-26s-28e
Eddy Co., NM
30-015-21398

Comments for Form C103 Location Inspection After P&A
18 March 2019

This well was plugged in preparation to drill a replacement Devonian SWD well on the same pad and reconstruct a new SWD facility on the same pad. The C103 subsequent P&A sundry notice was approved by NMOCD 2/26/2019. Since we're going to use the existing pad for the new replacement well and facilities, no additional remediation or reclamation is necessary.

The replacement well is called the Salt Cedar 16 State SWD 1 and is located 1850' FNL, 2185' FEL in Section 16-26s-28e approximately 243' northwest of the SRO 102 SWD location.

We are awaiting final approval of our C108 for the Salt Cedar 16 State SWD 1 and Mr. McMillan (NMOCD Santa Fe) told us he needs to see the approved C103 Location Inspection After P&A form (final P&A release) before he can approve the C108 for the Salt Cedar 16 St SWD 1. We also mailed the C101 drilling permit for the Salt Cedar 16 St SWD 1 on 3/13/2019. We are respectfully requesting an expedited approval of the C103 Location Inspection After P&A so we can get the final approval on our C108 and drill this well as soon as the C108 and C101 are approved.