

District 2-Artesia Field Office  
 811 S. 1<sup>st</sup> Street  
 Artesia, NM 88210  
 (Office) 575-748-1283  
 (Fax) 575-748-9720  
 Submit 1 Copy

**State of New Mexico**  
**EMNRD-OIL CONSERVATION DIVISION**

**BRADENHEAD TEST REPORT**

Operator Name Mesquite SWD, Inc.	<sup>30</sup> API Number 30-015-43806
Property Name Uber East SWD	Well No. 1

**7. Surface Location**

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
I	24	23S	31E	2345	S	660	E	Eddy

**Well Status**

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES <input type="radio"/> NO <input checked="" type="radio"/>	YES <input type="radio"/> NO <input checked="" type="radio"/>	INJ <input type="radio"/> SWD <input checked="" type="radio"/>	OIL <input type="radio"/> GAS <input type="radio"/>	6/4/2019


**OBSERVED DATA**

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure					
<b>Flow Characteristics</b>					
Puff	Y/ N	Y/ N	Y/ N	Y/ N	CO2 _____
Steady Flow	Y/ N	Y/ N	Y/ N	Y/ N	WTR _____
Surges	Y/ N	Y/ N	Y/ N	Y/ N	GAS _____
Down to nothing	Y/ N	Y/ N	Y/ N	Y/ N	If applicable type
Gas or Oil	Y/ N	Y/ N	Y/ N	Y/ N	fluid injected for
Water	Y/ N	Y/ N	Y/ N	Y/ N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	<b>OIL CONSERVATION DIVISION</b>
Print name: Rusty Parker	Recorded online:
Title:	Re-test:
E-mail Address: Accepted for record - NMOCD Phone # DS 6-19-19	
Date:	Witness: