RECEIVED

IU	Ν	2	8	2	0'	19

	JUN 2 8 2019							
Submit Che Copy To Appropriate District	State of New Mexico Form C-103							
Office I	Energy, Minerals and Nat	uDISRESOTICASTES	AO.C.D.	Revised November 3, 2011				
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO.					
811 S. First St., Artesia, NM 88210	N DIVISION ancis Dr.	30-015-23177 5. Indicate Type of Lease						
District III 1000 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE							
District IV	6. State Oil & Gas							
1220 S. St. Francis Dr., Santa Fe, NM 87505								
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSAI DIFFERENT RESERVOIR. USE "APPLICAT		LUG BACK TO A		Unit Agreement Name NTAL A STATE				
PROPOSALS.) 1. Type of Well: X Oil Well C		8. Well Number #8						
2. Name of Operator	· ·	9. OGRID Number						
EOG RESOURCES, INC		7377						
3. Address of Operator PO BOX 2267 MIDLAN	· .	10. Pool name or Wildcat						
4. Well Location			· · · · · · · · · · · · · · · · · · ·					
Unit Letter I: 2310 fee	et from the SOU <u>TH</u> line and <u>99</u>	00 feet from the EAS	<u>ST</u> line					
	<u>S_Range 29E_NMPM</u>	County EDDY						
	11. Elevation (Show whether D. 3376' GL			en de la caracteria de la La caracteria de la caracteri				
12. Check Appropriate Box to I	ndicate Nature of Notice, J	Report or Other D	ata					
NOTICE OF INTI		SUB	SEQUENT REF					
1	PLUG AND ABANDON	REMEDIAL WOR						
		COMMENCE DRI		PANDA				
PULL OR ALTER CASING		CASING/CEMEN						
	• :							
OTHER: All pits have been remediated in c	ompliance with OCD rules and	the terms of the One	eady for OCD inspe	ection after P&A				
\square An pits have been remediated in c \square Rat hole and cellar have been fille	and leveled. Cathodic protect	tion holes have been	properly abandoned	a closure plan.				
A steel marker at least 4" in diame	eter and at least 4' above ground	d level has been set in	concrete. It shows	the				
				•				
	SE NAME, WELL NUMBER,							
	<u>, TOWNSHIP, AND RANGE.</u> ED ON THE MARKER'S SU		<u> DN HAS BEEN WE</u>	<u>CLDED OR</u>				
	D ON THE MARKER 5 50	MACE.						
The location has been leveled as n	early as possible to original gro	und contour and has	been cleared of all j	unk, trash, flow lines and				
other production equipment. Anchors, dead men, tie downs and	3. Risers Not	+ Remove	ed.					
\square Anchors, dead men, tie downs and	I risers have been cut off at leas	t two feet below grou	ind level.	tod in compliance with				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed								
from lease and well location. \mathcal{G}_{ur} All metal bolts and other materials			ved. (Poured onsite	concrete bases do not have				
to be removed.) All other environmental concerns	TASL Not	lenoved		•				
All other environmental concerns Pipelines and flow lines have beer			All fluids have bee	en removed from non-				
retrieved flow lines and pipelines.		17.15.55.10 100010	. Thi fluids have bee					
If this is a one-well lease or last re	maining well on lease: all elect	rical service poles an	d lines have been re	moved from lease and well				
location, except for utility's distribution infrastructure.								
When all work has been completed, ret	urn this form to the appropriate	e District office to sch	edule an inspection.					
-V m				· - ·				
SIGNATURE May Ma	Iddly	REGULATORY SPI	ECIALIST DATE	6/27/2019				
TYPE OR PRINT NAME: KAY MA	ADDOX E-MAIL: kay ma	ddox@eogresources.	com PHONE: 4	32-686-3658				
For State Use Only			(31				
	ENIED	NENI	EN	DATE 7/3/19				
APPROVED BY: Conditions of Approval (if any):				DATE // 3/19				