State Of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor Sarah Cottrell Propst Cabinet Secretary Todd E. Leahy, JD, PhD Deputy Cabinet Secretary

Adrienne Sandoval Division Director

"Response Required - Deadline Enclosed"

Field Inspection Program "Preserving the Integrity of Our Environment"

01-Aug-19

LIME ROCK RESOURCES II-A, L.P. 1111 Bagby Street

Suite 4600 Houston, TX 77002

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

Inspection DateType InspectionInspectorCorrective Action Due ByInspection No.8/1/2019Routine Inspection[DRS] Danny Smolik10/30/2019iDRS1921337438

 Violations:

 Rule
 Violation

 19.15.16.8 Sign on Wells
 Inaccurate Information

 Comment:
 No API number on sign

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By." date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

Oil Conservation Division * 811 S. First St. * Artesia, NM 88210 Phone: 575-748-1283 * Fax: 575-748-9720 * www.emnrd.state.nm.us



LETTER OF VIOLATION - Field Inspection