State Of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor Sarah Cottrell Propst Cabinet Secretary Todd E. Leahy, JD, PhD Deputy Cabinet Secretary

Adrienne Sandoval Division Director

<u>"Response Required - Deadline</u> <u>Enclosed"</u>

Field Inspection Program "Preserving the Integrity of Our Environment"

01-Aug-19

LIME ROCK RESOURCES II-A, L.P.

1111 Bagby Street Suite 4600 Houston, TX 77002

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-015-28539] WEST RED LAKE UNIT #057			OGRID: 277558	P-06-18S-27E 280 FSL 850 FEL
Inspection Date	Type Inspection	Inspector	Corrective Action Due By	Inspection No.
8/1/2019	Routine Inspection	[DRS] Danny Smolik	10/30/2019	iDRS1921340274

 Violations:

 Rule
 Violation

 19.15.16.8 Sign on Wells
 Inaccurate Information

 Comment:
 Comment

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

No API number on sign

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

Oil Conservation Division * 811 S. First St. * Artesia, NM 88210 Phone: 575-748-1283 * Fax: 575-748-9720 * www.emnrd.state.nm.us



LETTER OF VIOLATION - Field Inspection