Submit One Copy To Appropriate District State of New Mexico Office District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 000 Rio Brazos Rd., Aztec, NM 87410 District IV 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505 1250 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT LISE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUIC BACK TO A				Form C-103 Revised November 3, 2011 WELL API NO. 30-015-10330 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. B-1159
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				 Lease Name or Unit Agreement Name Sunray State Well Number
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator COG Operating LLC				9. OGRID Number 229137
 3. Address of Operator 2208 W Main Artesia NM 88210 4. Well Location 				10. Pool name or Wildcat Red Lake; Qn-GRBG-SA
Unit Letter L 1650 feet from the South line and 978 feet from the West line Section 27 Township 17S Range 28E NMPM Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3681' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN			SUBS REMEDIAL WORK COMMENCE DRILI CASING/CEMENT	
OTHER: □ </td				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. <i>Power Lines/Poles</i> $M \neq Removed$ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. <i>Burged</i> Cables 6, <i>Power Pole Not Removed</i> All metal bolts and other materials have been removed? Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) <i>Burged Wight 29, 80272492 - 104.17009235</i> All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.				
When all work has been complet	ed, return this form to t		istrict office to scheo gulatory Technician	dule an inspection. DATE 8/9/2019
TYPE OR PRINT NAME Delila For State Use Only			pres2@concho.com	PHONE: 575-748-6946
APPROVED BY: Conditions of Approval (if any):	DENIED	TITLE	DENIE	D DATE 8/14/17