

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMLC028793A
6. If Indian, Allottee or Tribe Name**SUBMIT IN TRIPLICATE - Other instructions on page 2**7. If Unit or CA/Agreement, Name and/or No.
NMNM88525X8. Well Name and No.
BURCH KEELY UNIT 967H9. API Well No.
30-015-39579-00-S110. Field and Pool or Exploratory Area
BURCH KEELY-GLORIETA-UPR YESC11. County or Parish, State
EDDY COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Deepen
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Alter Casing
	<input type="checkbox"/> Hydraulic Fracturing
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Change Plans
	<input type="checkbox"/> Plug and Abandon
	<input type="checkbox"/> Convert to Injection
	<input type="checkbox"/> Plug Back
	<input type="checkbox"/> Production (Start/Resume)
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Recomplete
	<input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Water Disposal
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Well Integrity
	<input checked="" type="checkbox"/> Other Venting and/or Flaring

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

BURCH KEELY UNIT SATELLITE A BATTERY

PERMIT APPROVAL: ELECTRONIC SUBMISSION #460205

ACTUAL GAS FLARED FOR THIS BATTERY FOR 4/3/2019 - 7/2/2019

APR
TOTAL FOR BATTERY = 0MAY
TOTAL FOR BATTERY = 0

RECEIVED

NOV. 05 2019

Accepted for record
NMOC

DISTRICT 7 - ARTESIA O.C.D.

11/13/19

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #485891 verified by the BLM Well Information System
For COG OPERATING LLC, sent to the Carlsbad
Committed to AFMSS for processing by PRISCILLA PEREZ on 10/01/2019 (20PP0008SE)

Name (Printed/Typed) DANA KING

Title SUBMITTING CONTACT

Signature (Electronic Submission)

Date 10/01/2019

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By _____	Title Accepted for Record	Date OCT 16 2019
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Jonathon Shepard Carlsbad Field Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #485891 that would not fit on the form

32. Additional remarks, continued

JUNE
TOTAL FOR BATTERY = 0

JULY
TOTAL FOR BATTERY = 0

NUMBER OF WELLS TO FLARE: 44

PLEASE SEE ATTACHED WELL LIST

REASON: UNPLANNED MIDSTREAM CURTAILMENT
PLANT SHUT DOWN DUE TO HLP OR PLANT MAINTENANCE

BURCH KEELY UNIT STATELLITE A BATTERY WELL LIST
 UPDATED: 04/03/2019

	WELL NUMBER	API NUMBER
BURCH-KEELY UNIT	85	30-015-21663
BURCH-KEELY UNIT	87	30-015-21662
BURCH-KEELY UNIT	88	30-015-21665
BURCH-KEELY UNIT	89	30-015-03079
BURCH-KEELY UNIT	90	30-015-03073
BURCH-KEELY UNIT	106	30-015-26890
BURCH-KEELY UNIT	107	30-015-03076
BURCH-KEELY UNIT	108	30-015-25668
BURCH-KEELY UNIT	110	30-015-03067
BURCH-KEELY UNIT	139	30-015-03102
BURCH-KEELY UNIT	141	30-015-03110
BURCH-KEELY UNIT	219	30-015-27726
BURCH-KEELY UNIT	220	30-015-27769
BURCH-KEELY UNIT	221	30-015-27764
BURCH-KEELY UNIT	222	30-015-27788
BURCH-KEELY UNIT	235	30-015-28584
BURCH-KEELY UNIT	245	30-015-28156
BURCH-KEELY UNIT	246	30-015-28330
BURCH-KEELY UNIT	247	30-015-28335
BURCH-KEELY UNIT	271	30-015-29301
BURCH-KEELY UNIT	276	30-015-29512
BURCH-KEELY UNIT	280	30-015-29921
BURCH-KEELY UNIT	282	30-015-29722
BURCH-KEELY UNIT	315	30-015-30642
BURCH-KEELY UNIT	324	30-015-32427
BURCH-KEELY UNIT	325	30-015-32428
BURCH-KEELY UNIT	326	30-015-32429
BURCH-KEELY UNIT	340	30-015-32757
BURCH-KEELY UNIT	344	30-015-32712
BURCH-KEELY UNIT	345	30-015-32713
BURCH-KEELY UNIT	363	30-015-32992
BURCH-KEELY UNIT	365	30-015-32867
BURCH-KEELY UNIT	376	30-015-33569
BURCH-KEELY UNIT	413	30-015-36209
BURCH-KEELY UNIT	415	30-015-37131
BURCH-KEELY UNIT	623	30-015-38561
BURCH-KEELY UNIT	624	30-015-39126
BURCH-KEELY UNIT	629	30-015-40705
BURCH-KEELY UNIT	631	30-015-38648
BURCH-KEELY UNIT	636	30-015-38558
BURCH-KEELY UNIT	637	30-015-40183
BURCH-KEELY UNIT	699	30-015-39551
BURCH-KEELY UNIT	966H	30-015-44067
BURCH-KEELY UNIT	967H	30-015-39579