

RECEIVED

JAN 10 2020

Submit One Copy To Appropriate District Office

State of New Mexico

Form C-103

District I  
1625 N. French Dr., Hobbs, NM 88240

EMNRD-OCD ARTESIA

Energy, Minerals and Natural Resources

Revised November 3, 2011

District II  
811 S. First St., Artesia, NM 88210

OIL CONSERVATION DIVISION

District III  
1000 Rio Brazos Rd., Aztec, NM 87410

1220 South St. Francis Dr.

District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

Santa Fe, NM 87505

WELL API NO. 30-015-27016
5. Indicate Type of Lease STATE X FEE
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name PAULINE ALB STATE
8. Well Number #1
9. OGRID Number 7377
10. Pool name or Wildcat SAND DUNES; DELAWARE, WEST

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well  Gas Well  Other

2. Name of Operator  
EOG RESOURCES, INC

3. Address of Operator  
PO BOX 2267 MIDLAND, TEXAS 79702

4. Well Location  
Unit Letter I : 1980 feet from the SOUTH line and 660 feet from the EAST line  
Section 32 Township 23S Range 31E NMPM County EDDY

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3370' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- PLUG AND ABANDON
- TEMPORARILY ABANDON
- CHANGE PLANS
- PULL OR ALTER CASING
- MULTIPLE COMPL

SUBSEQUENT REPORT OF:

- REMEDIAL WORK
- ALTERING CASING
- COMMENCE DRILLING OPNS.
- P AND A
- CASING/CEMENT JOB

OTHER:

Location is ready for OCD inspection after P&A

- All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.**

- The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. *Buried Power Line Not Removed*
- Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. *Power Pole Anchor not removed*
- All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) *Trash in Pasture & in Bushes Not Removed*
- All other environmental concerns have been addressed as per OCD rules.
- Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. *Concrete Not Removed!*
- If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

BELOW GROUND HOLE MARKER INSTALLED

SIGNATURE Kay Maddox TITLE: REGULATORY SPECIALIST DATE 01/09/2020

TYPE OR PRINT NAME: KAY MADDOX E-MAIL: kay\_maddox@egoresources.com PHONE: 432-686-3658  
For State Use Only

DENIED

DENIED

APPROVED BY: \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 1/21/20

Conditions of Approval (if any):