| Submit 1 Copy To Appropriate District Office RECEVER | f New Mexico Is and Natural Resourc | HNGIC | Form C-103 | |
|--|--|-----------------------------|--|--|
| | | | Revised July 18, 2013 | |
| 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVI | | N 30-015-45279 | | |
| District III - (505) 334-6178 1000 Rio Brazos Rd - Aztec NM 87410 FMNRD-6265 | ch Se Sympois Dr. | 5. Indicate Type STATE | e of Lease FEE | |
| <u>District IV</u> – (505) 476-3460 Santa 1220 S. St. Francis Dr., Santa Fe, NM | Fe, NM 87505 | 6. State Oil & C | | |
| 87505 | | | | |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A | | A | 7. Lease Name or Unit Agreement Name | |
| DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | Palmillo 21 State | _ | |
| 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator | | 8. Well Number | | |
| Apache Corporation | | 9. OGRID Num 873 | ber | |
| Address of Operator Solution Address of Operator Midland, TX 79705 | | | 10. Pool name or Wildcat Winchester Bone Spring West (97569) | |
| 4. Well Location |) | vvinchester Bone | Spring West (97569) | |
| Unit Letter E: 1715 feet from th | e North line a | nd 370 feet from | om the West line | |
| Section 21 Township | | NMPM | County Eddy | |
| 11. Elevation (Show | whether DR, RKB, RT, C | GR, etc.) | | |
| The state of the s | | | | |
| 12. Check Appropriate Box to | Indicate Nature of N | otice, Report or Othe | r Data | |
| NOTICE OF INTENTION TO: | | SUBSEQUENT RE | EPORT OF: | |
| PERFORM REMEDIAL WORK PLUG AND ABANDO | | | ALTERING CASING | |
| TEMPORARILY ABANDON | | CE DRILLING OPNS. | P AND A | |
| DOWNHOLE COMMINGLE | | | | |
| CLOSED-LOOP SYSTEM OTHER: | OTHER: | completion amended | | |
| 13. Describe proposed or completed operations. (Clea | rly state all pertinent deta | ails, and give pertinent da | tes, including estimated date | |
| of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. | .7.14 NMAC. For Multi | ple Completions: Attach | wellbore diagram of | |
| proposed completion of recompletion. | | | | |
| Apache completed the following work | | 0.040450 | | |
| 8/2/19- perform casing test for 5 min to 6,100 psi toe sleeve of 8/2-8/10/19 perf 7481-12070 and frac stages1-27 TLR=163, | 785 bbl, 100mesh=5,656 | 5,310 lbs,20/40 =1,234,500 |) lbs | |
| 8/14-8/15/19 drill out plugs 8/26/2019- run 2 7/8 tubing set @7079 | | | | |
| B/27/2019 wait on facilities | | | | |
| 9/23/2019 Turn well over to production | | | | |
| | | | | |
| | | | | |
| | | | | |
| Spud Date: 12/7/2018 Ris | Release Date: 2/2/20 | 40 | | |
| Spud Date: 12/7/2018 Rig | Release Date: 2/2/20 | 19 | | |
| | | | | |
| I hereby certify that the information above is true and comp | lete to the best of my kno | owledge and belief. | | |
| Course (Illinic tub | Cr Ctaff Dog Angle | _1 | 4/7/0000 | |
| | TLE Sr. Staff Reg Analys | | ATE 1/7/2020 | |
| | mail address: alicia.fulton | @apachecorp.com P | HONE: (432) 818-1088 | |
| For State Use Only | | | _ | |
| APPROVED BY Conditions of Approval (If any): | LE Greelog | 13 4. DA | ATE 1-29-2020 | |