Submit 1 Copy To Appropriate District RECEIVED State of New Mexi Office District I – (575) 393-6161 Energy, Minerals and Natura 1625 N. French Dr., Hobbs, NM 88240 JAN 0 9 2020 OIL CONSERVATION D District II – (575) 748-1283 OIL CONSERVATION D District III – (505) 334-61 WNRD-OCDAR DESIAh St. Franci 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505	I Resources DIVISION is Dr.	Form C-103 Revised July 18, 2013 WELL API NO. 30-015-45381 5. Indicate Type of Lease STATE V FEE 6. State Oil & Gas Lease No. 317303
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)	BACK TO A SUCH	7. Lease Name or Unit Agreement Name PALMILLO 14-15 STATE
1. Type of Well: Oil Well 🔽 Gas Well 🗌 Other		8. Well Number 307H
2. Name of Operator Apache Corporation		9. OGRID Number 873
3. Address of Operator		10. Pool name or Wildcat
303 Veterans Airpark Lane, Suite 1000 Midland, TX 79705		WINCHESTER; BONE SPRING, WEST
4. Well Location Unit Letter M : 631 feet from the S	054	
	line and	
Section 14Township 19SRangII. Elevation (Show whether DR, R	e 28E	NMPM County EDDY
The Elevation (Snow whether Dr, R	KB, KI, GK, elc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB COMMENCE DRILLING OPNS. P AND A DOWNHOLE COMMINGLE OTHER: OTHER: casing pressure exception Z 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Production casing test per 19.15.16.10 (I) was conducted to 6100 psi for 5 minutes, successfully demonstrated integrity. Test did not meet requirements of 10(i) in that test did not extend for 30 minutes. Discussed issue with Ray Podany, he suggested C-103 for exception to requirement for this well. We have put procedures in place to make sure that the production casing is tested for 30 minutes as per rule for all future wells.		
Spud Date: 5/12/2019 Rig Release Date:		
I hereby certify that the information above is true and complete to the best SIGNATURE GRACIES TITLE Sr. Staff R		DATE 1/7/2020
Type or print name Alicia Fulton For State Use Only E-mail address:	alicia.fulton@apach	PHONE: (432) 818-1088
APPROVED BY TITLE TITLE Conditions of Approval (if any):	log ist	DATE 1-29-2020
		1/29/20 KS