Submit One Copy To Appropriate District State of New Mexico		Form C-103
Office District I RECEIVED State of New Mexico	rces Revi	sed November 3, 2011
1625 N. French Dr., Hobbs, NM 88249 1 0 2020	WELL API NO.	
	ON 5. Indicate Type of Lea	ise
811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Rd., FAMNROTOCD ARTES OSouth St. Francis Dr. District IV Santa Fe, NM 87505	STATE	FEE
District IV Santa Fe, NM Santa Fe, NM 87505	6. State Oil & Gas Leas L-6381	3e No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Curisbud Blute Com	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 1	
2. Name of Operator	9. OGRID Number	
COG Operating LLC	229137	
3. Address of Operator 2208 W Main Artesia NM 88210	10. Pool name or Wildo Purple Sage; Wolfcamp	
4. Well Location	r urpic sage, woncamp	Gas
Unit Letter <u>E 2140</u> feet from the <u>North</u> line and <u>990</u> feet from the West	ine	
Section <u>16</u> Township <u>22S</u> Range <u>27E</u> NMPM <u>Eddy</u> County		
11. Elevation (Show whether DR, RKB, RT 3105' GR	GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
	NCE DRILLING OPNS.	DA 🗌
PULL OR ALTER CASING MULTIPLE COMPL CASING CASING	CEMENT JOB	
	tion is ready for OCD inspection	after P&A
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 		
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 		
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. $n/1$ $h/1$		
other production equipment. Meter House / Run Not Removed Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. $\mathcal{R} = \{A, A, A$		
from lease and well location. \mathcal{R}_{15e-75} \mathcal{N}_{5} \mathcal{L}_{1} \mathcal{R}_{1} \mathcal{R}_{2} \mathcal{R}_{2		
to be removed.) The show on been addressed as per OCD rules.		
 All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.1 	NMAC All fluids have been rem	oved from non
retrieved flow lines and pipelines. Concrete Rieces on location	+ 10 Astus Not	Re to aver
retrieved flow lines and pipelines. Concrete Pieces on locatio-	poles and lines have been removed	I from lease and well
location, except for utility's distribution infrastructure.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
· ALITA		
SIGNATURE	echnician DATE 2	2/4/2020
TYPE OR PRINT NAME Delilah Flores E-MAIL: dflores2@cc	ncho.com PHONE: 575	-748-6946
For State Use Only	GC CC	. 4
APPROVED BY:	DAT	TE 3/2/20
Conditions of Approval (if any):		

 $\frac{1}{7}$