7772737475767				
OTITE A PARTY OF THE PARTY OF T				
Submit 3 Copies To Appropriate District Office	State of New Me	0\		Form C-103
District I	Energy de linerals and linerals	ral Resources	WELL API NO.	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	RECEIVED		30-015-10258	1
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSORVATION	DIVISION	5. Indicate Type of Lease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Frad	74.	STATE VXX FI	
District IV	Santa Fe, NM 87	25/	6. State Oil & Gas Lease N	0.
1220 S. St. Francis Dr., Santa Fe, NM 87505	128293037	132	1964 P&A	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agr Harris State	eement Name
PROPOSALS.)  1. Type of Well: Oil Well Gas Well X Other Re-Entry of P&A well			0 777 11 3 7 1	
			9. OGRID Number	·
2. Name of Operator Sandel Operating Company			226685	
3. Address of Operator			10. Pool name or Wildcat	
P. O. Box 10487, Midland Texas 79702			Antelope Sinl	(Upper Penn)
4. Well Location				
Unit Letter P : 660 feet from the South line and 660 feet from the East line				
Section 36 Township 18S Range 23E NMPM County Eddy				
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3830' KB  Pit or Below-grade Tank Application   or Closure   See C-144				
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN	TENTION TO:	SUBS	SEQUENT REPORT (	)F
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	·	
TEMPORARILY ABANDON	ABANDON CHANGE PLANS COMMENCE DRIL			
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB				
OTHER:		OTHER:		
	leted operations. (Clearly state all p		give pertinent dates, includir	ng estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
07-07-06: Drill out float collar and hard cement to 467' (7' below shoe). Tested Liner and shoe to 1000 psig for 30				
minutes, OK. Drilled out CIBP at 1095' K.B.				
Reamed and washed down to 5970', pipe stuck, pulled free. Cleaned out and drilled down 5575', pipe stuck. Ran				
chemical cutter and cut off and pulled 2-7/8" tubing at 5356'; left 10' piece of 2 7/8" tubing, (4) 4-3/4" DC, (2) 6" DC				
and 6-1/4" bit from 5356' to 5552' K.B. Received verbal P&A instructions from Van Barton with the NMOCD				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines XX a general permit  or an (attached) alternative OCD-approved plan.				
SIGNATURE Shery J.	JODO TITLE A	agent for San	del OperatingDATE_	08/08/06
Type or print name Sheryl L. For State Use Only	Jonas E-mail add	dress: Sjonas40	11@ao1.comTelephoneN	o. 432–683–5511
Approver	ted for record - NMOGPILE			طمليان
APPROVED BY:  Conditions of Approval (if any):	TATALOGRAPHE		DATE	0/21/100